

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction:

04-01-2002

Application ID:

285822

Certificate Number:

Type: Ho

233826

Occupancy Type:

Residential

Building Type:

House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified

Inspector/TDI Inspector:

Roof

Entire Re-Roof

October 7, 2002

Appointed

Qualified

Inspector

Location of Property to be Insured:

Street:

Lot:

Block:

Tract or

Addition:

3708 AVENUE O 1/2

City:

County:

State:

GALVESTON

GALVESTON

TEXAS

Inside City Limits

Seaward - SEAWARD - ASCE 7-93

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.



Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104

(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction:

12-08-2011

Application ID:

676626

Certificate Number:

617414

Occupancy Type:

Residential

Building Type:

House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Additions

Bedroom

March 30, 2012

Appointed

Qualified

Inspector

AT REAR (NORTH) OF HOUSE

Location of Property to be Insured:

Lot:

Block:

Tract or Addition:

Street:

3708 AVENUE O 1/2

City:

GALVESTON

County:

State:

GALVESTON

TEXAS

Inside City Limits

Seaward - SEAWARD - 2006 IRC Intl Residential Code

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.



Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction:

09-11-2019

Application ID:

2169333

Certificate Number:

2169333

Occupancy Type:

Residential

Building Type:

House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Alterations

Replace Window(s)

October 9, 2019

Appointed

Qualified

Inspector

Number of Windows: 12, Location: 1st Floor- 4 Left; 2nd Floor- 3 Front, 1 Left, 2 Rear, 2 Right

Location of Property to be Insured:

Tract or

Street:

Lot:

Block:

Addition:

3708 AVENUE O 1/2

City:

County:

State:

GALVESTON

GALVESTON

TEXAS

Inside City Limits

Seaward - Seaward - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the ongoing improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.