



TEXAS DEPARTMENT OF INSURANCE
Regulatory Policy Division - Windstorm Inspections Program (104-WS)
333 Guadalupe, Austin, Texas 78701 * PO Box 149104, Austin, Texas 78714-9104
(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 01-16-2020

Application ID: 2177796 Certificate Number: 2177796

Occupancy Type: Residential Building Type: House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Roof Entire Re-Roof January 17, 2020 TDI Inspector

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

2845 N Remington Dr

City:

County:

State:

Angleton Brazoria TEXAS

Inside City Limits

Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas

Revisions)

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the ongoing improvement identified in the certificate complies with the