

## Property Condition Report

<b>Case Number:</b> 512-309203	<b>Contract Area:</b> 2D
<b>Current Step:</b> 1c-Ready to Show Condition	<b>Address:</b> 976 LAKE VIEW CIR W
<b>Step Date:</b> 02/06/2020	<b>City, St Zip:</b> BROOKSHIRE, TX 77423-0000
<b>HOC:</b> Denver	

### Property Condition Report

Item Description/Condition	Item Functionality	Functionality/Test Notes
<b>Cooling/Air-Conditioner:</b> OK --Heating/Furnace: OK --HVAC System Duct: OK	<b>HVAC tested and functional?:</b> Yes	HVAC blowers tested and functional with generator bypass.
<b>Electrical Wiring:</b> OK --Other: OK --Other: N/A	<b>Electric supply tested and functional?:</b> Yes	Property successfully energized with generator bypass.
<b>Stove/Range/Oven:</b> OK --Kitchen Cabinets: OK --Other: Damaged	<b>Built-in appliances tested and functional?:</b> No	Appliances tested and functional. Refrigerator is damaged.
<b>Plumbing:</b> OK --Sink: OK --Other: N/A	<b>Water supply tested and functional?:</b> Yes	Plumbing holds pressure.
<b>Water Heater:</b> OK	<b>Water heater functional?:</b> Yes	Water heater shows no signs of leaks.
<b>Sewer/Septic System:</b> OK --Toilet: OK --Other: N/A	<b>Sanitary &amp; plumbing system functional?:</b> Yes	Toilets force flushed with no backup. Antifreeze pour successful.
<b>Roof:</b> OK --Other: OK	<b>Roofing in acceptable condition?:</b> Yes	Roof appears in good condition with no active leaks.