



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 * PO Box 149104, Austin, Texas 78714-9104
(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction:

Application ID: 186031 **Certificate Number:** 149621

Occupancy Type: Residential **Building Type:** House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

New New (Entire Building) February 4, 1999 Appointed Qualified Inspector

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

605 WESTWOOD CIRCLE 3 1

City:

County:

State:

LA MARQUE GALVESTON TEXAS

Inside City Limits Inland - SSBC-Southern Standard Building Code



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104
(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 07-06-2005

Application ID: 375098 Certificate Number: 324174

Occupancy Type: Residential Building Type: House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Additions Living Area September 22, 2005 Appointed Qualified Inspector AT REAR OF HOUSE

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

605 WESTWOOD CIRCLE 3 1

City:

County:

State:

LA MARQUE GALVESTON TEXAS

Inside City Limits Inland I - INLAND I - 2003 IRC Intl Residential Code



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 * PO Box 149104, Austin, Texas 78714-9104
(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 01-15-2002

Application ID: 261622 Certificate Number: 215433

Occupancy Type: Residential Building Type: Detached Garage

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

New New (Entire Building) February 21, 2002 Appointed Qualified Inspector

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

605 WESTWOOD CIRCLE 3 1

City:

County:

State:

LA MARQUE GALVESTON TEXAS

Inside City Limits Inland I - INLAND I - ASCE 7-93



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 * PO Box 149104, Austin, Texas 78714-9104

(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 01-01-1999

Application ID: 293799 Certificate Number: 241644

Occupancy Type: Residential Building Type: House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

New New (Entire Building) January 6, 2003 Appointed Qualified Inspector

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

605 WESTWOOD CIRCLE 3 1

City:

County:

State:

LA MARQUE GALVESTON TEXAS

Inside City Limits Inland I - INLAND I - ASCE 7-93



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104

(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 08-06-2013

Application ID: 737840 Certificate Number: 673674

Occupancy Type: Residential Building Type: House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Roof Entire Re-Roof October 11, 2013 Appointed Qualified Inspector

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

605 WESTWOOD CIRCLE 3 1

City:

County:

State:

LA MARQUE GALVESTON TEXAS

Inside City Limits Inland I - INLAND I - 2006 IRC Intl Residential Code



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)
333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104
(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 08-06-2013

Application ID: 737840

Certificate Number: 673673

Occupancy Type: Residential

Building Type: Detached Garage

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Roof Entire Re-Roof October 11, 2013 Appointed Qualified Inspector

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

605 WESTWOOD CIRCLE 3 1

City:

County:

State:

LA MARQUE GALVESTON TEXAS

Inside City Limits Inland I - INLAND I - 2006 IRC Intl Residential Code



TEXAS DEPARTMENT OF INSURANCE

Regulatory Policy Division - Windstorm Inspections Program (104-WS)

333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104

(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction: 08-06-2013

Application ID: 737840 **Certificate Number:** 673675

Occupancy Type: Residential **Building Type:** Pool House

Certificate Type:

Certificate Detail:

Certificate Date:

Appointed Qualified Inspector/TDI Inspector:

Roof Entire Re-Roof October 11, 2013 Appointed Qualified Inspector

Location of Property to be Insured:

Street:

Lot:

Block: Tract or Addition:

605 WESTWOOD CIRCLE 3 1

City:

County:

State:

LA MARQUE GALVESTON TEXAS

Inside City Limits Inland I - INLAND I - 2006 IRC Intl Residential Code