AIR CONDITIONIN GEHEATING TACLB009039E PO Box 218683 Houston, TX 77218 (281) 579-1120 ghac@swbell.net				Invoice			
				DATE	0	06/29/2020	
				INVOICE#	103050		
				TERMS	Cas	h On Delivery	
BILL TO				PRIMARY SERVICE LOCATION			
4030 Duccio River Way Katy, TX 77493				4030 Duccio River Way Katy, TX 77493			
JOB#	DATE	PO/REF#	DESC	CRIPTION			
37934582	cl C In B A In C C C C I S Ta Ta C		6/29/20 - 9-11am - pb - New Customer, Selling house needs the AC checked. 1-System \$90.00				
			Inspec Blew o Addeo Inspec CONE check All ma 132/3 Sc-9.0 Tamps Capao	Completion Notes: Performed AC check up Inspected evaporate coil Blew drain lines Added bleach tabs down primary line Inspected drain pan CONDENSER UNIT checked pressure and amps All major electrical components 132/315 Sc-9.0 Tamps-7.2 Capacitor 45x5mfd Washed unit			
			Outsic	Outside unit need suction wrap on 7/8 copper			
Job Charges				Qty	Rate	Total	
RESSHVAC Residential Se	rvice HVAC			1.00	\$90.00	\$90.00	
Job Subtotal						\$90.00	
Job Total						\$90.00	
PRE-WORK SIGNATURE				I	POST-WORK SIG	NATURE	
	CUSTOMER ME	SSAGE		Invoice Total:		\$90.00	

Thank you

Deposits (-):

Total Due:

\$0.00

Payments (-): \$90.00

\$0.00

1