

# Air Conditioner



an NRG company

PO Box 540487  
Houston, TX 77254  
1.855.457.5700

# Receipt

**Work Order Number:** WO-00548061  
**DATE:** 07/18/2018 1:57 PM

**Case Number:**  
**Technician:** Terry Miles

## PREPARED FOR:

Elizabeth Walla  
3510 Norris Dr Houston, TX 77025  
(713) 471-7297  
betsywalla.fashion@gmail.com

## WORK PERFORMED

Upon arrival check system in attic for air and water leaks inspect secondary pan is rusted and no float switch installed, check pressures at condenser unit system is low on freon r22 and condenser coil is deteriorating, leaks in condenser coil

## WORK ORDER DETAILS

<b>Total Project Cost</b>	\$6,812.80
<b>Warranty Coverage</b>	\$1,500.00
<b>Cost to Homeowner</b>	\$5,312.80

## PAYMENT DETAILS

Form Of Payment	Payment Date	Payment Amount	Transaction Id
Credit Card	07/18/2018 1:56 PM	\$5,312.80	61191148138

## AUTHORIZED PARTS

**Total Line**

Part	Unit Price	Qty	Price	Coverage	Amount Due
Box Coil and Condenser Combo, Ruud, 16 SEER, 4 ton	\$6,275.00	1	\$6,275.00	\$1,500.00	\$4,775.00
Permit & City Inspection	\$299.00	1	\$299.00	\$0	\$299.00
Difficult Access	\$238.80	1	\$238.80	\$0	\$238.80
<b>Total</b>					<b>\$5,312.80</b>


**ADDITIONAL LINE ITEM DETAIL**

Part	Description	Included Parts
Box Coil and Condenser Combo, Ruud, 16 SEER, 4 ton	5 year labor, 5 year parts/equipment, must register for 10 year parts and equipment	
Permit & City Inspection	City building code enforcement mandated inspection permit fee	
Difficult Access	Task code for difficult access	

**ADDITIONAL RECOMMENDED WORK**

Recommend replacing system condenser and evaporater with new and more efficient equipment for lower energy consumption consumption

Customer Signature:



**Terms and Conditions**

By signing this page and/or acknowledging the check box on the signature screen, Customer agrees and/or acknowledges that:

1. Reliant Energy Retail Services, LLC (Service Company), will perform the services described in this agreement.