

Certificate of Compliance WPI-8

Location of Property to be Insured

Street: 220 BUFFALO TRAIL Block: City: Lake Jackson Lot: Tract or Addition:

County: BRAZORIA

Inside City Limits Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

Date of Construction: 07-01-2015					
Application ID: 2003291	Certificate Number: 2003291				
Occupancy Type: Residential	Building Type: House with Garage Attached by Breezeway				

Roof Entire Re-Roof August 8, 2015

Appointed Qualified Inspector

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.



Certificate of Compliance WPI-8

Location of Property to be Insured

 Street:
 220 BUFFALO TRAIL
 Lot:

 Block:
 Tract or Addition:
 Tract or Addition:

 City:
 Lake Jackson
 County:
 BRAZORIA

 Inside City:
 Line:
 County:
 BRAZORIA

Date of Construction: 06-29-2016			
Application ID: 2054368	Certificate Number: 2054368		
Occupancy Type: Residential	Building Type: House with Garage Attached by Breezeway		
Alterations Replace Window(s) October 10, 2016	Appointed Qualified Inspector Number of Windows: 11, Location: 4 FRONT, 3 LEI		
EAR, 2 RIGHT			

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.

TDI Texas Department of Insurance

Certificate of Compliance WPI-8

Location of Property to be Insured

Street:	220 BUFFALO TRAIL	Lot:	14		
Block:	C	Tract or Addition:			
City:	Lake Jackson	County	: BRAZORIA		
Inside City Limits					
Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)					

Date of Construction: 10-06-2016						
Application ID: 2061611	tion ID: 2061611 Certificate Number: 2061611					
Occupancy Type: Residential	Building Type: House with Garage Attached by Breezeway					
Alterations Exterior Wall Covering (Siding) Decembe	er 16, 2016 Appointed Qualified Inspector	Location: Garage Only, Type (EX				
vl, Wood, Fiber, Cement): HARDI PLANK						
yi, wood, fiber, cement, fiandri Lank						
Alterations Replace Door(s) December 16, 2016	Appointed Qualified Inspector Number of Door	rs: 1, Location: LEFT SIDE OF				
RAGE, Impact: Non-Impact, Is Windborne Debris Protection Available On-Site: Yes, Comments: 1 DOUBLE DOOR						

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.