



# Certificate of Compliance WPI-8

### Location of Property to be Insured

**Street:** 1468 SEAGULL

**Lot:**

**Block:**

**Tract or Addition:**

**City:** SARGENT

**County:** MATAGORDA

Inside City Limits

Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

**Date of Construction:** 07-06-2016

**Certificate Number:** 2044977

**Application ID:** 2044977

**Occupancy Type:** Residential

**Building Type:** House

**Repairs:** Piling(s) July 12, 2016 Appointed Qualified Inspector Due to: Deterioration, List Repair: REPLACED PILINGS, Location: ROW ROW 2 - 3; ROW 3 - 3

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.

as Administ



# Certificate of Compliance WPI-8

**Location of Property to be Insured**

**Street:** 1468 SEAGULL

**Lot:**

**Block:**

**Tract or Addition:**

**City:** SARGENT

**County:** MATAGORDA

Inside City Limits

Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

**Date of Construction:** 10-08-2018

**Application ID:** 2158219

**Certificate Number:** 2158219

**Occupancy Type:** Residential

**Building Type:** House

Alterations    Replace Window(s)    June 4, 2019    Appointed Qualified Inspector    Number of Windows: 10, Location: 1st Floor- 2 Right; 2n  
or- 2 Front, 2 Left, 2 Rear, 2 Right

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the ongoing improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.