


# Canchola Services Foundation Repair

## Site Survey



Notes:

- Exterior
- Exterior/Breakout
- Interior/Breakout

Address: 10818 Seneca St. Houston, TX 77016

Client: Alex Gallardo

Exterior Piers: 21

Interior/Breakouts Piers: N/A

Exterior/Breakouts Piers: N/A

Total Piers: 21