

Certificate of Compliance WPI-8

Location of Property to be Insured

Street: 109 SUGAR CANE TRACE

Block:

City: LAKE JACKSON

Lot:

Tract or Addition:

County: BRAZORIA

Inside City Limits

Inland I - INLAND I - 2006 IRC Intl Residential Code

Date of Construction: 10-01-2008

Application ID: 527394

Occupancy Type: Residential

Certificate Number: 464108

Building Type: House

Repairs Framing January 3, 2009 Appointed Qualified Inspector LEFT SIDE GABLE FRAMING & SIDING RESET ON WALL FRAMING
REQUIRED WITH METAL CONNECTORS

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.