




Customer:	MD America	Name of Pit:	North Zulch Pond
Customer Contact:	Shane Barnett	Lat:	30.935571
Date:	03/17/18	Long:	-96.122673
Time Survey Started:	1:00 PM	Mapped Volume (bbls):	761,104
Time Survey Completed:	5:00 PM	Mapped Area (sq ft):	820,320
Water Type:	<input type="checkbox"/> FW <input type="checkbox"/> FB <input checked="" type="checkbox"/> PW	Box number installed:	N/A
Average Depth (ft.):	5.1	Sensor depth reading at time of install:	N/A
Max Survey Depth (ft.):	13.9	Water elevation at time of install:	N/A
Gauge Pole Present:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Gauge Pole Reading:	N/A
Boat Reading at Gauge Pole		Notes:	
JHA Completed	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		N/A

Maps:





Technician: Damion Smith
Email: dsmith@selectenergyservices.com
Phone: (210)400-4701