

Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104

(800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

Certificate of Compliance WPI-8

Date of Construction:

03-01-2018

Application ID:

2109226

Certificate Number:

2109226

Occupancy Type:

Residential

Building Type:

House

Certificate Type:

Certificate Detail:

Certificate Date:

Inspector/TDI Inspector:

Appointed Qualified

New

New (Entire Building)

January 15, 2019

Appointed

Qualified

Inspector

Location of Property to be Insured:

Tract or

Street:

Lot:

Block:

Addition:

220 BENTWATER LANE

11

WOODSHORE 4

City:

County:

State:

Clute

BRAZORIA

TEXAS

Inside City Limits

Inland I - Inland I - International Residential Code, 2006 Edition (Amended with 2006 Texas Revisions)

his Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 210.2515 and demonstrates that the ongoing improvement identified in the certificate complies with the applicable windstorm building code nder 28 Texas Administrative Code §§ 5.4007 - 5.4011.