**Property Condition Report** 

Case Number: 512-017763 Contract Area:

**Current Step:** 

1c-Ready to Show Condition

3014 HEATHERGLEN RD

Step Date:

03/02/2021

Address: City, St Zip: MONTGOMERY, TX 77356-0000

2D

HOC: Denver

Property Condition Report				
Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-ConditioneHeating/Furnace:HVAC System Duct:	r: OK OK OK	HVAC tested and functional?:	Yes	HVAC blowers tested and functional with generator bypass.
Electrical Wiring:Other:Other:	OK OK N/A	Electric supply tested and functional?:	Yes	Property successfully energized with generator bypass.
Stove/Range/Oven:Kitchen Cabinets:Other:	OK OK OK	Built-in appliances tested and functional?:	Yes	Appliances tested and functional.
Plumbing: Sink: Other:	OK OK N/A	Water supply tested and functional?:	Yes	Plumbing holds pressure.
Water Heater:	ОК	Water heater functional?:	Yes	Water heater shows no signs of leaks or rust.
Sewer/Septic System: Toilet: Other:	OK OK N/A	Sanitary & plumbing system functional?:	Yes	Antifreeze pour successful.
Roof: Other:	OK OK	Roofing in acceptable condition?:	Yes	Roof appears in good condition with no active leaks.