


**Note: Job still in progress**



NiteOwl Restoration  
PO BOX 1164  
Tomball, TX 77375  
832-593-1600

**Ramiro Lopez**  
**24503 Hartwick Falls Dr, porter, TX 77365**

# Job#: NO19-Lopez,R

RestoReports Link: <http://www.restoreports.com/reports/8754>

---

## Readings

---

### Entry Readings

Date: 09/24/2019

User Jason Scott

Moisture Readings A: 99 B: 99 C: 99

Room Readings Temp In: 73 RH In: 69 GPP In: 84.9

Equipment Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0

Notes

Date: 09/25/2019

User Jason Scott

Moisture Readings A: 69 B: 59 C: 66

---

**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0

**Notes**

**Date:** 09/26/2019

**User** Jason Scott

**Moisture Readings** A: 29 B: 22 C: 19

**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7

**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0

**Notes**

**Date:** 09/27/2019


**User** Jason Scott

**Moisture Readings** A: 7 B: 4 C: 7

**Room Readings** Temp In: 90 RH In: 32 GPP In: 67.3

**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0

**Notes**



**Entry Photos & Documents**

No items found

## Formal Dining Readings

Date: 09/24/2019

**User** Jason Scott  
**Moisture Readings** A: 99 B: 99 C: 99  
**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/25/2019

**User** Jason Scott  
**Moisture Readings** A: 63 B: 68 C: 66  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 33 B: 34 C: 34  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**


Date: 09/27/2019

**User** Jason Scott  
**Moisture Readings** A: 4 B: 6 C: 7  
**Room Readings** Temp In: 90 RH In: 32 GPP In: 67.3  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0

**Notes**

**Average Moisture (Formal Dining :**

33.00  
25  
20.5  
20.75



**Formal Dining Photos & Documents**

No items found

**Garage Readings**

Date: 09/24/2019

**User** Jason Scott  
**Moisture Readings** A: 99 B: 99 C: 99  
**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 4 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/25/2019

**User** Jason Scott

**Moisture Readings** A: 65 B: 61 C: 55  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 4 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**


**Date:** 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 24 B: 22 C: 34  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 4 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

**Date:** 09/27/2019

**User** Jason Scott  
**Moisture Readings** A: 4 B: 5 C: 7  
**Room Readings** Temp In: 90 RH In: 32 GPP In: 67.3  
**Equipment** Air Mover: 4 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

**Average Moisture (Garage)**



## Garage Photos & Documents

No items found

## Kitchen Readings

Date: 09/24/2019

**User** Jason Scott  
**Moisture Readings** A: 99 B: 99 C: 99  
**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 4 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/25/2019

**User** Jason Scott  
**Moisture Readings** A: 69 B: 66 C: 67  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 4 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 33 B: 21 C: 34  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 4 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/27/2019


User Jason Scott

Moisture Readings A: 5 B: 7 C: 7

Room Readings Temp In: 90 RH In: 32 GPP In: 67.3

Equipment Air Mover: 4 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0

Notes



### Kitchen Photos & Documents

No items found

### Kitchen Hall/ Pantry Readings

Date: 09/24/2019

User Jason Scott

Moisture Readings A: 99 B: 99 C: 99 D: 99



**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0

**Notes**

**Date:** 09/25/2019

**User** Jason Scott

**Moisture Readings** A: 61 B: 59 C: 53 D: 51

**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7

**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0

**Notes**

**Date:** 09/26/2019

**User** Jason Scott

**Moisture Readings** A: 19 B: 21 C: 24 D: 26

**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7

**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0

**Notes**

**Date:** 09/27/2019

**User** Jason Scott


**Moisture Readings** A: 7 B: 4 C: 5 D: 7

**Room Readings** Temp In: 90 RH In: 32 GPP In: 67.3

**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0

**Notes**

### Average Moisture (Kitchen Hall/ Pantry)



□ Ceiling Reading    ○ Wall Reading    △ Floor Reading

### Kitchen Hall/ Pantry Photos & Documents

No items found

### Laundry Readings

Date: 09/24/2019

User Jason Scott

Moisture Readings A: 99 B: 99

Room Readings Temp In: 73 RH In: 69 GPP In: 84.9

Equipment Air Mover: 2 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0

Notes

Date: 09/25/2019

User Jason Scott

**Moisture Readings** A: 69 B: 66  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 2 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

**Date:** 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 22 B: 24  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 2 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

**Date:** 09/27/2019

**User** Jason Scott  
**Moisture Readings** A: 4 B: 7  
**Room Readings** Temp In: 90 RH In: 32 GPP In: 67.3  
**Equipment** Air Mover: 2 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

Average Moisture (Laundry)

JR



Ceiling Reading    Wall Reading    Floor Reading

## Laundry Photos & Documents

No items found

### Living Room Readings

Date: 09/24/2019

**User** Jason Scott  
**Moisture Readings** A: 99 B: 99 C: 99  
**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/25/2019

**User** Jason Scott  
**Moisture Readings** A: 66 B: 64 C: 61  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 21 B: 22 C: 23  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/27/2019

User Jason Scott


Moisture Readings A: 7 B: 6 C: 7

Room Readings Temp In: 90 RH In: 32 GPP In: 67.3

Equipment Air Mover: 3 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0

Notes

### Average Moisture (Living Room)



### Living Room Photos & Documents

No items found

### Master Bathroom/ Closet Readings

Date: 09/24/2019

User Jason Scott

Moisture Readings A: 99 B: 99 C: 99 D: 99

**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 5 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

**Date:** 09/25/2019

**User** Jason Scott  
**Moisture Readings** A: 69 B: 55 C: 49 D: 41  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 5 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**



**Date:** 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 19 B: 24 C: 26 D: 37  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 5 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

**Date:** 09/27/2019

**User** Jason Scott  
**Moisture Readings** A: 4 B: 7 C: 5 D: 6  
**Room Readings** Temp In: 90 RH In: 32 GPP In: 67.3  
**Equipment** Air Mover: 5 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

### Average Moisture (Master Bathroom/ Closet)



### Master Bathroom/ Closet Photos & Documents

No items found

### Master Bedroom Readings

Date: 09/24/2019

**User** Jason Scott  
**Moisture Readings** A: 99 B: 99 C: 99 D: 99  
**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 6 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/25/2019

**User** Jason Scott

**Moisture Readings** A: 68 B: 61 C: 54 D: 58  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 6 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**


**Date:** 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 21 B: 18 C: 24 D: 19  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 6 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

**Date:** 09/27/2019

**User** Jason Scott  
**Moisture Readings** A: 7 B: 7 C: 5 D: 4  
**Room Readings** Temp In: 90 RH In: 32 GPP In: 67.3  
**Equipment** Air Mover: 6 Axial: 0 Dehumidifier: 1 Negative Air Fan: 0 Other: 0  
**Notes**

Average Moisture (Master Bedroom)



□ Ceiling Reading    ○ Wall Reading    △ Floor Reading



## Master Bedroom Photos & Documents

No items found

## Office Readings

Date: 09/24/2019

**User** Jason Scott  
**Moisture Readings** A: 99 B: 99 C: 99  
**Room Readings** Temp In: 73 RH In: 69 GPP In: 84.9  
**Equipment** Air Mover: 2 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/25/2019

**User** Jason Scott  
**Moisture Readings** A: 69 B: 66 C: 61  
**Room Readings** Temp In: 84 RH In: 50 GPP In: 87.7  
**Equipment** Air Mover: 2 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/26/2019

**User** Jason Scott  
**Moisture Readings** A: 31 B: 29 C: 34  
**Room Readings** Temp In: 87 RH In: 43 GPP In: 82.7  
**Equipment** Air Mover: 2 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0  
**Notes**

Date: 09/27/2019

User Jason Scott


Moisture Readings A: 4 B: 6 C: 7

Room Readings Temp In: 90 RH In: 32 GPP In: 67.3

Equipment Air Mover: 2 Axial: 0 Dehumidifier: 0 Negative Air Fan: 0 Other: 0

Notes


### Average Moisture (Office)



### Office Photos & Documents

No items found

### Average Moisture (All Rooms)



### Additional Photos & Documents

No items found

<http://www.restoreports.com/reports/8754>

©2011-2019 RestoReports.com. All Rights Reserved.