


18918 Squirrel Oaks Drive


Being Lot 4, in Block 2, Glen Oaks, Section One (1), a subdivision of 23.29 acres of land in the Cyrus T. Ward Survey, A-612, Montgomery County, Texas, according to the map or plat thereof recorded in Cabinet V, Sheets 76 and 77, of the Map Records of Montgomery County, Texas.




Fidelity National Title
Insurance Company

LEGEND

- 1/2" ROD FOUND
- ⊗ 1/2" ROD SET
- 5/8" ROD FOUND
- ⊗ "X" FOUND/SET
- ⊕ 60d NAIL FOUND
- FENCE POST FOR CORNER
- CM CONTROLLING MONUMENT
- AC AIR CONDITIONER
- PE POOL EQUIPMENT
- TE TRANSFORMER PAD
- BRICK COLUMN
- POWER POLE
- ▲ UNDERGROUND ELECTRIC
- △ OVERHEAD ELECTRIC
- OHP— OVERHEAD ELECTRIC POWER
- OES— OVERHEAD ELECTRIC SERVICE
- CHAIN LINK
- WOOD FENCE 0.5' WIDE TYPICAL
- I — IRON FENCE
- □ — DOUBLE SIDED WOOD FENCE
- /// EDGE OF ASPHALT
- ▴ — EDGE OF GRAVEL
- ▨ CONCRETE
- ▨ COVERED AREA



GRAND OAKS/ GLEN OAKS
HOME OWNERS ASSOCIATION, INC.
FILM CODE NO. 119-11-2237



EXCEPTIONS:

NOTE: PROPERTY SUBJECT TO TERMS, CONDITIONS, AND EASEMENTS CONTAINED IN INSTRUMENT RECORDED IN CAB. V, SHEETS 76 AND 77, CC#'S 2004047546, 2009055293, 2010012633, 2015021990, 2015021991

NOTES:

NOTE: BEARINGS, EASEMENTS AND BUILDING LINES ARE BY RECORDED PLAT UNLESS OTHERWISE NOTED.

FLOOD NOTE: According to the F.I.R.M. No. 48339C0475 G, this property does lie in Zone X and does not lie within the 100 year flood zone.

This survey is made in conjunction with the information provided by Fidelity National Title Insurance Company. Use of this survey by any other parties and/or for other purposes shall be at user's own risk and any loss resulting from other use shall not be the responsibility of the undersigned. This is to certify that I have on this date made a careful and accurate survey on the ground of the subject property. The plat hereon is a correct and accurate representation of the property lines and dimensions as indicated; location and type of buildings are as shown; and EXCEPT AS SHOWN, there are no visible and apparent encroachments or protrusions on the ground.

Drawn By: OR

Scale: 1" = 20'

Date: 09/02/15

Borrower: BELL, III

GF No.: FTH-12-FAH15005372AP

Job No. 1513890

C.B.G. Surveying, Inc.

12025 Shiloh Road, Ste. 250

Dallas, TX 75228

P 214.349.9485

F 214.349.2216

Firm No. 101688

www.cbqdfw.com



Accepted by: _____
Purchaser

Date: _____

Purchaser