

12005.

APPROXIMATELY 5 FOOT HOUSE ENCROACHMENT INTO 20 FOOT BUILDING LINE GRANTED AN 8 FOOT INCROACHMENT OF HOME INTO 10 FOOT WIDE REAR BUILDING LINE GRANTED

FAIRWAY

110.59

10

P

2880

0/0

57

SA 2

4

m

0,

N.W.

(B)

P. 1

10.83

8.4

CABLE

LOT 16, BLOCK 2, DESCRIPTION

BRIDGES

FOUNTAINS OF NORTHGATE FOREST,

15906

A SUBDIVISION IN HARRIS COUNTY, TEXAS

R=375.00' \(\O=01040'34''\)
L=10.97'

(B)

ELEVATIONS BASED ON TSARP DATUM, RM 110070,

FOUND

ALL

5/8"IRON RODS

R=25.00' O=48°11'23" L=21.03'

ELEVATION 103.58 (2001 ADJUSTMENT).

SP ECTRUM DEVELOPERS

OWNER:

R=50.00' 0=63°05'39' L=55.06'

O DENOTES MONUMENTS OF RECORD DIGNITY AS DESCRIBED

FLOOD ZONE "X"
FEMA MAP 48201CQ265M
DATE 01.08.17

×į


SEAL Sept.

IN OR ON RECORDED DOCUMENTS

Alvin R. Hiroms Registered Professional Land Surveyor No. 4209

SURVEYING 8

Y ROMS



RYE NAMO

ARI

A COM

ZO

09022020

ndr

%0.

000.000

This map or plat (survey) copyright 09·21·20 by Hiroms Surveying Co. This survey is provided solely for the use of current parties (the purchaser herein described and all parties necessary to this transaction). p.o. box 5394 kingwood, texas (281)-360-5080

I, Alvin R. Hiroms, a Registered Professional Land Surveyor in the State of Texas, do hereby certify that the above property has been surveyed by me or under my supervision, is correct, that the property monuments have been set, left as found, or referenced, that the property has access to a public roadway, and that there are no intrusions upon or protrusions from this property unless shown; and that this survey conforms to the Texas Society of Professional Land Surveyors' Requirements for a CATEGORY A. CONDITION 3 Súrvey.

SGALE: I": REVISED:06·22·21 □△℃電 09・21・20 207