

Boundary Survey ***1425122*** ***1425122***





RLS #: 10-02-0007 CLIENT #: 1425122-H015

FIELD DATE: 2/2/10

DRAFTER: LGS

APPROVED: NJF

SCALE: 1" = 30'

ADDRESS

10322 Chevy Chase Drive Houston, Texas 77042

LEGAL DESCRIPTION: (AS FURNISHED)

Lot 9, Block 1, Corrected Plat of Briar Court, Vol. 257, Pg. 111, Harris County, Texas, Map Records

BASIS OF BEARINGS: As to Recorded Plat

LIST OF POSSIBLE ENCROACHMENTS: The Fences do not follow the Lot lines

SURVEYOR INFORMATION:

U. S. SURVEYING COMPANY, INC. HOUSTON, TEXAS 77073 (281)443-9288 FAX:(281)443-9224







SURVEYOR FILE NUMBER: 12-6085

The Certified Registered Professional Land Surveyor signic certifies the accuracy and sufficiency of the survey p

CERTIFIED TO: (AS FURNISHED)

First American Title Insurance Company Lori Higgins

*AS TO PLAT

AC: AIR CONDITIONER
BLIDG: BUILDINE
BLIDG: BUILDINE
BLIDG: CONCETE
BLIDG: BUILDINE
BLIDG: BUILDIN

SURVEYOR'S CERTIFICATE

I, C. N. Fauquier, Texas Registered Professional Land Surveyor No. 4372, do hereby certify that the survey plat hereon is a representation of the property hereon described, and do further state that this survey depicts the visible improvements to said property as located on the ground, and that there are no visible encroachments onto said property by any such visible improvements except as shown hereon.

