

	J	V	\mathbf{A}		\sim
Z, rì.				\perp N	
	FΟ	UN	DΑ	T10	N

ame/Own	er:				 	
ddress:	3/57/	trover	Ah i	Home Phone:		

TE _____ MAP# _

Work Phone/ Other:

RESTORATION TYPE: EXT 29 INT 101	BUILDING DESCRIPTION STORY BRICK GRADE BEAM DEPTH	BREAK-OUTS CRAWL / CONV P&B / B&B
\$300/day fine		
\$300/day fine if not 100% complete by 4/21/16.		
THE STATE OF THE S	× ×. ×	·
×		X
××		×
X XX		× ×
X	G.	*
*		*
X Zac		x x

○ EXTERIOR● INTERIOR○ BUILDER PIERS

X PREVIOUS WORK
PE POOL EQUIPMENT
G GAS LINE

--/--/-- FENCE

WALL CRACKS

[A/C] A/C UNIT

SLOPE SLEAN OUT