Property Highlights



110 Long Meadow Ct. Clute, TX

Upgrades During Construction:

- -Upgraded granite and higher grade cabinets
- -Full bathroom added to upstairs guest bedroom
- -Full Gutters
- -3rd Garage
- -Door added in back of garage leading to backyard
- -Wood floors/ upgraded padding and carpet
- -Fireplace
- -Jetted Tub
- -Wrought Iron Balusters
- -Additional window added next to front door