


**24535 Emerald Pool Falls.
Dafnis Moreno.**

PPC

7. Cut in the ceiling.



NOOK

8. Details of paint on the wall.

OWNER'S SUITE

9. Relocate the tower hanger near to the closet from the edge of the wall to inside.

10. Details of paint on the closet.

Fauref

BATHROOM

11. Damage baseboard next to the tub.

12. Detail of paint on door frame and door.

13. Mixed colors silicone (white and beige) between wall and marble sinks. It should be only beige.

First Floor

GARAGE

1. Details of paint and finished walls on the perimeter of garage.
2. Stained garage's floor.

LAUNDRY ROOM

3. Details of paint on the door frame and door.

KITCHEN

4. Details of paint at the corner of the refrigerator area.
5. Scratch in the finished ceiling by a hanging lamp.
6. Plug misfitted.

STUDY

14. Detail of paint on the wall near to the doors.
15. Edges of the glass on the door.
16. Detail on the edge of the window.


FOYER

17. Detail of the finished wall.
18. Detail of paint on the wall.
19. Hallway Switch curved.

PANTRY

20. Details on the baseboard of the pantry between the wall and the wood.

24535 Emerald Pool Falls. Dafnis Moreno.



Second Floor

GAME ROOM

- 21. Cuts in the ceiling.
- 22. Detail of paint on the wall.

BY THE STAIRS

- 23. There is a stain at the middle of the wall next to the stairs.

BEDROOM 4 & BATHROOM

- 24. Plug out in the hallway
- 25. Holes in the wall of the shower.
- 26. Missing silicone between wall and marble sink.
- 27. Details on frame door.

JACK AND JILL BATHROOM & CLOSET

- 28. Missing silicone between walls and marble sinks.
- 29. Details of the finished wall on closets. Pretty bad finished wall.
- 30. Detail of paint on frame door.

BEDROOM 2

- 32. Detail of paint on wall and frame door.

Robert Smith

[Signature]

01/21/2014