

M&L Septic Services

No. 2166

14096 Eden Lane
 Willis, TX 77378
 936-203-4422 or 936-760-6396
 mlseptic38@gmail.com

DATE 9/6/2021 – 9/8/2021
ORDER NO

NAME Brandon Smith	PHONE 281-536-6399
ADDRESS (Site) 14354 Strausie Ln. Conroe, TX 77302	

SOLD BY	<input type="checkbox"/> REAL ESTATE INSPECTION	<input type="checkbox"/> TEST & REPORTING CONTRACT
	<input type="checkbox"/> NEW INSTALL	<input type="checkbox"/> REPAIR

QUANTITY	DESCRIPTION	AMOUNT
	1) Request to inspect water logged well and determine it if will start pumping. I recommended a Water Well Service. 2) Next to physically locate the septic tank, found behind the house about a foot down. Located behind the enclosed patio on the Southeast side. 3) Followed the only drain/field lines from the House, around the big oak tree on the North side of the House to the back of the property which was about 100 ft. 4) Preformed a visual inspection of the tank and performed a 90 minute sludge test. After 90 minutes running test water thru the system the conventional system was performing. Septic System does not need to be pumped out.	
	4 Hours Labor	\$395
	Total Due	\$395

IF YOU ARE USING A CREDIT CARD, PLEASE CALL THE OFFICE AT 936-760-6396

ALL CLAIMS AND RETURNED
 GOODS MUST BE ACCOMPANIED
 BY THIS BILL

OWNER SIGNATURE _____

ALL CLAIMS AND RETURNED
GOODS MUST BE ACCOMPANIED
BY THIS BILL

OWNER SIGNATURE _____