

| | |
|-------------|---|
| 2010 & 2011 | Office Addition (closed in atrium) |
| | Added Window |
| | Replaced Ceiling Fan |
| | Added Crown Molding |
| | Replaced Base Boards |
| | Replaced Wood Flooring |
| | Repainted Walls, Base Boards & Crown Molding |
| 2019 | Repainted Walls, Base Boards & Crown Molding |
| | Replaced Wood Flooring |
| 2010 & 2011 | Foyer |
| | Replaced Front Door with Side Lights |
| | Replaced Ceiling lighting |
| | Replaced Wood Flooring |
| | Added Crown Molding |
| | Replaced Base Boards |
| | Repainted Walls, Base Boards & Crown Molding |
| 2019 | Repainted Walls, Base Boards & Crown Molding |
| | Replaced Wood Flooring |
| 2013 | Added Replaced Patio |
| | Lighting and Ceiling Fan |
| 2019 | Updated with Hardi Board & Replaced Paint |
| | Garage |
| 2017 | Replaced built in closet (3 - huge) |
| | Replaced built work station area |
| | Additional Improvements |
| 2016 | Completely Painted Outside of House |
| 2018 | Replaced Drive |
| 2018 | Replaced Garage Door |
| 2016 | Replaced Roof |
| 2016 | Replaced Gutters |
| 2015 | Replaced A/C (in and outside units) |
| 2013 | Foundation Repair |
| 2010 & 2011 | Replaced Electrical Plugs / Switches inside / outside of complete house |
| 2010 & 2011 | Replaced Outside Lighting Fixtures |
| 2015 | Replaced Wooden Fence |
| 2015 | Replaced Rod Iron Gate |
| 2016 | Entire Home Re-Plumbed |
| 2019 | Replaced Hot Water Heater |
| 2018 | Replaced Wooden Fence |
| 2021 | Replaced Srubs, Plants and Mulched Flower Beds |
| | Sprinkler System |

Date of Remodel/Improvement

2010 & 2011 **Kitchen / Breakfast Area**

Replaced Cabinets
Replaced Granite Countertop
Replaced Wall Tile Back Splash
Pantry Addition
Replaced Porcelain Flooring
Replaced All Kitchen Appliances
Replaced Granite Kitchen Sink / Faucet
Added Additional Hot Water Tank
Under Kitchen Sink
Replaced Light Fixtures - Ceiling and Under Cabinets
Replaced Windows with Double Pane Windows
Replaced Door Leading to Garage
Added Crown Molding
Replaced Base Boards
Repainted Walls, Base Boards & Crown Molding
2021 Replace Garbage Disposal

2010 & 2011 **Living Room / Family Room**

Added Raised Ceiling to Tray Ceiling
Replaced Lighting and Ceiling Fan
Replaced Windows with Double Pane Windows
Replaced Wood Flooring
Added Crown Molding
Replaced Base Boards
Repainted Walls, Base Boards & Crown Molding
2019 Repainted Walls, Base Boards & Crown Molding
Replaced Wood Flooring

2010 & 2011 **Dining Room**

Replaced Wood Flooring
Added Crown Molding
Replaced Base Boards
Repainted Walls, Base Boards & Crown Molding
2019 Repainted Walls, Base Boards & Crown Molding
Replaced Wood Flooring

2010 & 2011 **Bathroom # 1 (Master)**

Replaced Cabinets
2 Replaced Sink / Faucet
Replaced Granite Countertop
Replaced Inside Doors
Replaced Windows with Double Pane Windows
Added Crown Molding
Replaced Base Boards
Repainted Walls, Base Boards & Crown Molding
Replaced Light Fixtures & Replaced Framed Mirror

| | |
|-------------|--|
| 2019 | Repainted Walls, Base Boards & Crown Molding |
| 2010 & 2011 | Bathroom # 2 |
| | Replaced Cabinets |
| | Replaced Sink / Faucet |
| | Replaced Granite Countertop |
| | Replaced Wood Flooring |
| | Replaced Inside Doors |
| | Added Crown Molding |
| | Replaced Base Boards |
| | Repainted Walls, Base Boards & Crown Molding |
| | Replaced Light Fixtures |
| | Replaced Framed Mirror |
| 2019 | Repainted Walls, Base Boards & Crown Molding |
| | Replaced Wood Flooring |
| 2010 & 2011 | Bedroom # 1 (Master) |
| | Replaced Inside Doors |
| | Replaced Outside French Door |
| | Replaced Ceiling Fan |
| | Added Crown Molding |
| | Replaced Base Boards |
| | Replaced Wood Flooring |
| | Repainted Walls, Base Boards & Crown Molding |
| 2019 | Repainted Walls, Base Boards & Crown Molding |
| | Replaced Carpet |
| 2010 & 2011 | Bedroom # 2 |
| | Replaced Inside Doors |
| | Replaced Outside French Door |
| | Replaced Ceiling Fan |
| | Added Crown Molding |
| | Replaced Base Boards |
| | Replaced Wood Flooring |
| | Repainted Walls, Base Boards & Crown Molding |
| 2019 | Repainted Walls, Base Boards & Crown Molding |
| | Replaced Wood Flooring |
| 2010 & 2011 | Bedroom # 3 |
| | Replaced Inside Doors |
| | Added Window |
| | Replaced Ceiling Fan |
| | Added Crown Molding |
| | Replaced Base Boards |
| | Replaced Wood Flooring |
| | Repainted Walls, Base Boards & Crown Molding |
| 2019 | Repainted Walls, Base Boards & Crown Molding |
| | Replaced Wood Flooring |