

COUNTY _____
CITY QUAD BLOCK LOT _____

42
26-29

NAME: _____ COUNTY: Harris
ADDRESS: 2402 Rutland CITY: Houston

ARCHITECT/BUILDER: _____ UTM: _____
DATE: c.1908-10 PERIOD: _____

OWNER: W. F. and Mary Williams STYLE: _____
2402 Rutland Houston, TX 77008 THEME: _____

DESCRIPTION: Cottage, frame, 1-story, combination roof with projecting gable end bay (shingled gable), attached porch supported by turned posts, simple, squared balusters, decorative bargeboard, brick piers under house.

BUILDING MATERIAL: wall: frame roof: asbestos
PHYSICAL CONDITION: good SITE: original or moved _____ date _____

ALTERATIONS: Small additions to rear.
SIGNIFICANCE: Good example of type of cottage typical of the area and the period; nice details.

AREA OF SIGNIFICANCE: _____ LEVEL OF SIGNIFICANCE: _____
DESIGNATION: NR NHL RTHL HABS HAER HESI HSI OTHER: _____
ORIGINAL USE: residence PRESENT USE: residence
RELATIONSHIP TO SURROUNDINGS: Large corner lot
ACREAGE/BOUNDARY DESCRIPTION: _____

BIBLIOGRAPHIC DATA: _____
SEE INFO/CORRESPONDENCE FILES: _____
RECORDED BY: EB/KL INFORMANT: _____
DATE: 1-16-80 PHOTO DATA: 1 - 35mm

(rev. 6-79)



United States Department of the Interior
National Park Service

National Register of Historic Places
Inventory—Nomination Form

For NPS use only

received

date entered

Continuation sheet

Item number 4, 7, 8, 10

Page 81

Site No. 81

NAME <u>House at ...</u>	COUNTY <u>Harris</u>	BLOCK <u>42</u>
ADDRESS <u>2402 Rutland st.</u>	CITY <u>Houston</u>	LOT <u>26-29</u>
	UTM <u>Zone 15 E 267,930 N 3,299,730</u>	
ARCHITECT/BUILDER <u>unknown</u>	DATE <u>1908-10</u>	PERIOD <u>1900--</u>
OWNER <u>J. C. Williams</u>	STYLE <u>Queen Anne influence</u>	
<u>2402 Rutland, Houston, Texas 77008</u>	THEME	

DESCRIPTION One-story frame cottage; hipped roof with projecting front gable over chamfered bay with three windows; gable end with round-butt shingles, small window with stained glass, and cut-out decorative vergeboard; front porch once wrapped around side, but outside corner has been enclosed; turned porch posts with square fretwork and balusters between; windows have one-over-one lights; house sits on brick piers spanned by lattice; interior brick chimney.

Building material: wallframe, clapboard roof asbestos

Physical condition good-significant site: original or moved date

Alterations Small additions to rear; intrusive burglar bars on front door,*

SIGNIFICANCE Good example of type of cottage typical of the area and the period; good and attractive detailing.

Area of significance architecture Level of significance local

DESIGNATION: NR NHL RTHL HABS HAER HESI HSI OTHER

ORIGINAL USE residence PRESENT USE residence

RELATIONSHIP TO SURROUNDINGS Well-kept yard with trees and bushes, on large corner lot; residential area.

ACREAGE/BOUNDARY DESCRIPTION less than one acre

BIBLIOGRAPHY

RECORDED BY E. Beasley and K. L. London INFORMANT

DATE January 16, 1980 PHOTO DATA 1 - 35 mm., Tex. Hist. Commission

*enclosed porch corner.



2402

2402 Rutland

81

Houston Heights

Site No. 81, 2402 Rutland

Houston, Texas 77008

Photo: K.L. London, January 16, 1980

On file, Texas Historical Commission

Front facade, looking east

Photo 102 of
127

102