

Tech notes: \_\_\_\_\_ #3

NAME Moser, Cecil ADDRESS 1835 CR 235  
No. 281-960-0514 77511

TYPE SYSTEM: AquaTrac Spray/ Drip Inspection: 4 month inspection

Control Panel - Alarm Audio ok Visual ok wiring/conduit- good  
timer: ok

Air Compressor filter ok Working - Air pressure good

LIFT STATION/HOLDING TANKS: YES OR NO  
Holding Tank: Scum \_\_\_\_\_"  
Liftstation/Dosing Sludge Level \_\_\_\_\_"  
Pump \_\_\_\_\_ Pump float: \_\_\_\_\_ Alarm float Audio \_\_\_\_\_ Visual -- \_\_\_\_\_

1st-Pre (trash) tank scum: 0"  
2nd-Aerobic tank scum: 0" Sludge - 2% Aeration: good  
3rd-Pump tank Sludge: 0"  
Pump function good  
Floats: Pump float ok Override float ok Alarm float ok  
Lids (all) ok Risers (all) ok Screw(s) replaced: 0  
Issues - tanks no. & sizes of lid/riser: \_\_\_\_\_

Spray: Chlorinator/liquid chlor (part): ok Chlorine tablets/liquid yes  
Pop-up/Sprinklers function ok Spray Area ok

Drip: Filters \_\_\_\_\_ Drip hoses \_\_\_\_\_ Vacuum breakers \_\_\_\_\_  
Field area: \_\_\_\_\_ Flush valves \_\_\_\_\_

Norweco-Bioketic-- \_\_\_\_\_ Zabel "yellow" filter \_\_\_\_\_  
Cleaned \_\_\_\_\_, last big cleaning (date) \_\_\_\_\_ Adjitator: Working: \_\_\_\_\_, Cleaned: \_\_\_\_\_

Test Results and observations:  
Chlorine Residual: \_\_\_\_\_  
Repairs & Comments: System functioning properly

Inspector: [Signature] Date: 01/27/22