

880 Bonita improvements

Sherwin Williams Duration paint—all interior

New carpet—all bedrooms

Installed new fencing on left side of home and iron fencing across bulkhead

Replaced Kitchen sink and faucet

Granite cleaned, polished and sealed

Luxury vinyl installed downstairs

New mini split installed downstairs (a/c and heat)

Installed gas line to home

Installed new gas cooktop

Gas line for dryer

Mosquito misting system

Bulkhead—brand new deadman and tie backs installed

Replaced all exterior stairs with one-piece solid wood treads

Replaced garage door

New MyQ Smart Garage Door Opener

New Ceiling Fans back porch, living room

New dining room light fixture

New lighted faucets in master bath

Hood vent above gas cooktop, vented outside

Roll down sun shades on upper porch and downstairs patio area

Wood privacy louvers behind hot tub