



PO Box 27056
Houston, TX 77227-7056
(281) 495-0051

AAA Leak Detection Services, Inc.

Locally Owned and Operated

INVOICE NO. 2190510	
ORDER TAKEN BY DDM	DATE OF ORDER 7-May-19
TECHNICIAN DDM	STARTING DATE 9-May-19
JOB NUMBER NA	COMPLETED DATE 9-May-19
SITE TELEPHONE NUMBER NA	
COMMENTS: Vacant house Pool only	

CUSTOMER REFERENCE NUMBER Ultima Pools - Jimmy	TELEPHONE NO. OF PARTY BILLED 832-860-6066 c
BILL TO ADDRESS Blake Hillegeist Real Estate 2813 Newman St Houston, TX 77098	SITE NAME AND ADDRESS Residence 14911 Bramblewood Dr Houston, TX 77079

DESCRIPTION OF WORK :

Pressure testing :

Pass	Fail	
X		Pool return line
X		Pool fitting glue joints
		Common pool return line
X		Polaris return line (disconnected)
X		Polaris wall fitting
		Spa / air return line
		Spa fitting glue joints
		Fountain return lines
		Weeping rock return line
		Spa fountain return line
X		Pool drain suction line (to filter)
		Pool drain suction line (to skimmer)
		Spa drain suction line
		Spa drain suction line to skimmer
X		Skimmer suction line (s)
		Skimmer equalizer suction line (s)
		Wall suction line
X		Backwash line

Dye testing :

Pass	Fail	
X		Pool return fittings
		Spa return fittings
X		Polaris fitting
		Wall sumps
X		Skimmer throat(s)
X		Skimmer housing(s)
	X	Light conduit (s) pool
		Light conduit (s) spa
X		Drain sump housing(s)
X		Drain sump ring(s)
X		Static plug (s)
X		Tile line
X		Bond beam
		Plaster crack(s) pool
		Plaster crack(s) spa

Epoxy seals :

	Pool return fitting(s)		Static plug (s)
	Spa return fitting(s)		Tile line
	Polaris fitting		Bond beam
	Wall suction fitting		Plaster crack(s) pool
	Skimmer throat(s)		Plaster crack(s) spa
	Skimmer housing(s)		
butyl tape	Light conduit (s) pool		
	Light ring (s) pool		
	Light conduit (s) spa		
	Light ring (s) spa		
	Drain sump housing(s)		
	Drain sump ring(s)		

Note: Epoxy seals are temporary repairs and are not guaranteed.



PO Box 27056
Houston, TX 77227-7056
(281) 495-0051

AAA Leak Detection Services, Inc.

Locally Owned and Operated

CUSTOMER REFERENCE NUMBER Ultima Pools - Jimmy		TELEPHONE NO. OF PARTY BILLED 832-860-6066 c	INVOICE NO. 2190510
BILL TO ADDRESS Blake Hillegeist Real Estate 2813 Newman St Houston, TX 77098		TECHNICIAN DDM	DATE OF ORDER 7-May-19
SITE NAME AND ADDRESS Residence 14911 Bramblewood Dr Houston, TX 77079		JOB NUMBER NA	STARTING DATE 9-May-19
DESCRIPTION OF WORK (continued) : Results : A leak was detected in the pool light conduit. The old butyl seal failed. The old seal was removed and replaced.		SITE TELEPHONE NUMBER NA	
GUARANTEE ON DETECTION: All work is guaranteed for 30 days from the date of completion. We will re-test the system or refund the detection fee (at our sole discretion) if reported within 30 days of completion. Liability is limited to the above and will not include consequential damages. GUARANTEE ON DETECTION does not apply to hourly work performed or out of town work. GUARANTEE ON REPAIRS: All repair work is guaranteed for 30 days. All repairs are guaranteed from the date of completion and will be limited to workmanship only. LATE FEE: Payment on all invoices are due upon receipt. Invoices not paid within 30 days of the invoice date will incur a late fee of 1 1/2% per month of the outstanding balance along with any charges for collection fees and attorney fees, in the event of default. A \$25.00 return check fee will be charged on all returned checks.		COMMENTS: Vacant house Pool only	
		TOTAL AMOUNT DUE IS PAYABLE ON PRESENTATION OF INVOICE	
		TOTAL AMOUNT DUE \$350.00	

Note: A 4% processing fee will be charged on all credit card charges.

Thank you for your business