

Certificate of Compliance WPI-8

Location of Property to be Insured

Street: 12303 23RD STREET

Block:

City: SANTA FE

Lot:

Tract or Addition:

County: GALVESTON

Inside City Limits

Inland I - INLAND I - 2006 IRC Intl Residential Code

Date of Construction: 05-15-2013

Application ID: 721773

Occupancy Type: Residential

Certificate Number: 656802

Building Type: House

Roof Entire Re-Roof June 3, 2013 Appointed Qualified Inspector

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.

Certificate of Compliance WPI-8

Location of Property to be Insured

Street: 12303 23RD STREET

Block:

City: SANTA FE

Lot:

Tract or Addition:

County: GALVESTON

Inside City Limits

Inland I - INLAND I - 2006 IRC Intl Residential Code

Date of Construction: 05-15-2013

Application ID: 721773

Occupancy Type: Residential

Certificate Number: 656803

Building Type: Detached Garage

Roof Entire Re-Roof June 3, 2013 Appointed Qualified Inspector

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.

Certificate of Compliance WPI-8

Location of Property to be Insured

Street: 12303 23RD STREET

Block:

City: SANTA FE

Lot:

Tract or Addition:

County: GALVESTON

Inside City Limits

Inland I - INLAND I - 2006 IRC Intl Residential Code

Date of Construction: 06-24-2013

Application ID: 728908

Occupancy Type: Residential

Certificate Number: 664300

Building Type: House

Alterations Exterior Wall Covering (Siding) August 3, 2013 Appointed Qualified Inspector SIDING - VINYL & HARDI PLANK ON
ONT SIDE AND EIGHT GABLE

Alterations Replace Garage Door(s) August 3, 2013 Appointed Qualified Inspector

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.