TRANSFER OF WARRANTY

In the event a change in ownership occur, assignment of this warranty to a new owner or owner must be accomplished no later than thirty (30) days after transfer of the title. Transfer must be made on this form with a transfer fee of \$150.00 dollars current the time of transfer.

To be completed at the time of sale and mailed along with the \$150.00 transfer fee, the entire original warranty and Xerox copy of the warranty deed to Bonilla Foundation Repair, Inc. 5326 Trafalgar, Houston, TX.77045.

ASSIGNMENT OF WARRANTY

| This is to certify that on 9.29 known as 3601 Wakeforest, in the City of be transferred from Frank Saltzman. | Houston, TX., 20 Houston, TX. Zip Code 77098 was or will |
|--|--|
| Executed this 29th days of 5 | aptembers, 20 14 |
| (Buyer) | Earl Melles (Buyer) |
| Jasan Medlery (Print Namo Buyer) | EMILY MEDCEY (Print Name Buyer) |
| (Seller) | (Seller) |
| This to certify that, by payment of the t | ransfer fee in the amount of \$ |

This to certify that, by payment of the transfer fee in the amount of secent of which is here by acknowledge, and on the facts contained above, the warranty has been transferred on the records of BONILLA FOUNDATION REPAIR, INC. to the new OWNER effective on the day of the title transfer.

FOUNDATION REPAIR LIFETIME WARRANTY

Bonilla Foundation Repair, Inc. Warrants to FRANK SALTZMAN that should settlement in excess of 1" in 30 (one inch in thirty feet) Occur where pilings were installed as shown on the contract elevation for the property know 3601 Wakeforest, in the city of Houston, TX Zip Code 77098 The releveling will be done at no additional cost to the owner, so long as all of the provisions of the contract are met.

This repair work was completed by Bonilla Foundation July 13 2013.

In the event change of ownership of this property occurs, assignment of this warranty to a new owner must be accomplished within (30) days of the transfer of title. Please mail this certificate with a copy of your warranty deed that you should receive at closing along with a \$ 150.00 dollars transfer fee to the above address.

SHOULD ASSIGNMENT NOT BE PROPERLY MADE, THIS WARRANTY IS VOID.

BONILLA FOUNDATION REPAIR, INC.

Bonille

Date 6-13-14

| Bonilla foundation Repair | | | 5326 Trafalgar Houston, TX 77045 | | | Phone: 713-434-8432 Fax: 713-434-8483 | | | |
|---|--------------|--------------|-------------------------------------|--------------|-------------------------|--|--------------|---|--|
| Customer FVANK S | altzman | 1000 | Date | 10 | www.bonillaf | oundationrep | air.com | | |
| Address 3100 Lnk | | | CARRIED I | 0x = 10' | -30-12 | | | | |
| HOUSTUM TR | 77098 Fax | | Downs | | | Sidin | Brick | | |
| (W) 832)725-5 | | | | | | Story | 2 | | |
| | | | | | | | | | |
| | | | | | | | | | |
| O, | * X 3 | 1) - (월4) | | | | | | | |
| * | | F P | | | | | | | |
| (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) | | A B | | | | | | | |
| | | -18 | | | | | | | |
| SD 1/2 | I MC | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Exterior Piling Interior Piling | | - | | | | | | | |
| 3 Brick Crack | • | 5 | | k required a | | -lace | • | | |
| | My | 6 | | | Removal/Re _l | nacement | ş | _ | |
| 4 Slab Crack | ~~~ | 7 | _ tunnet i | Footage | | | \$ | | |