


30926 Imperial Walk Lane

Being Lot Thirty-one (31), in Block One (1), of Imperial Oaks Park, Section Ten (10), a subdivision in Montgomery County, Texas, according to the map or plat thereof, recorded in Cabinet X, Sheet(s) 196 of Map Records of Montgomery County, Texas.

LEGEND

- 1/2" ROD FOUND
- ⊗ 1/2" ROD SET
- 5/8" ROD FOUND
- ⊗ "X" FOUND/SET
- POINT FOR CORNER
- FENCE POST FOR CORNER
- CM CONTROLLING MONUMENT
- AC AIR CONDITIONER
- PE POOL EQUIPMENT
- TE TRANSFORMER PAD
- BRICK COLUMN
- POWER POLE
- ▲ UNDERGROUND ELECTRIC
- △ OVERHEAD ELECTRIC
- OHP— OVERHEAD ELECTRIC POWER
- OES— OVERHEAD ELECTRIC SERVICE
- CHAIN LINK
- WOOD FENCE 0.5' WIDE TYPICAL
- I— IRON FENCE
- X — BARBED WIRE
- / — EDGE OF ASPHALT
- / — EDGE OF GRAVEL
- CONCRETE
- COVERED AREA



Survey Received and Accepted by

X _____
 X _____
 X _____
 Date _____

EXCEPTIONS:

NOTE: PROPERTY SUBJECT TO TERMS, CONDITIONS, AND EASEMENTS CONTAINED IN INSTRUMENT RECORDED IN CAB. X, SH'S 196 THROUGH 197, CC FILE NO'S 8446986, 9219247, 9252428, 2005065513, 20070332430, 2010033603, 2011062393, 2011090919, 2011111276, 2011111277, 2011112119, 2013089984, 2013104114, 2013104115, 2013104116, 2013134415, 2014023232, 2014107025, 2014117443, 2014123530

NOTES:

NOTE: BEARINGS, EASEMENTS AND BUILDING LINES ARE BY RECORDED PLAT UNLESS OTHERWISE NOTED.

FLOOD NOTE: According to the F.I.R.M. No. 48339C0545 G, this property does lie in Zone X and does not lie within the 100 year flood zone.

This survey is made in conjunction with the information provided by Trueline Technologies. Use of this survey by any other parties and/or for other purposes shall be at user's own risk and any loss resulting from other use shall not be the responsibility of the undersigned. This is to certify that I have on this date made a careful and accurate survey on the ground of the subject property. The plat hereon is a correct and accurate representation of the property lines and dimensions as indicated; location and type of buildings are as shown; and EXCEPT AS SHOWN, there are no visible and apparent encroachments or protrusions on the ground.

Drawn By: C.C.

Scale: 1" = 20'

Date: 05/06/15

GF No.: 7695-15-2033

Job No. 1506246

C.B.G. Surveying, Inc.

12025 Shiloh Road, Ste. 230


Dallas, TX 75228

P 214.349.9485

F 214.349.2216

Firm No. 10168800

www.cbgsfw.com



Accepted by: _____
 Date: _____
 Purchaser
 Purchaser