Home Repairs – February 2023 2738 S. Cedar Hollow Dr. Pearland, TX 77584

- ❖ Patch all holes in walls
- Fix cabinet in bathroom
- Replace Toilet seat covers
- Remove all broken blinds
- Patch and paint holes from blinds
- ❖ Fix sheet rock in game room and upstairs bathroom
- Downstairs bathroom cabinet
- ❖ Touch up paint throughout the home
- Humidifier on wood floor
- ❖ Seal all windows