

## Texas Department of Insurance

Regulatory Policy Division - Windstorm Inspections Program (104-WS) 333 Guadalupe, Austin, Texas 78701 ★ PO Box 149104, Austin, Texas 78714-9104 (800) 248-6032 | F: (512) 490-1051 | TDI.texas.gov | @TexasTDI

## Certificate of Compliance WPI-8

			WPI-8
Date of Const	ruction: 08-01	-2014	
Application ID	: 762801	Certificate Numb	per: 762801
Occupancy Ty	<b>pe:</b> Residentia	l Building Ty	ype: House
Certificate Type:			
Certificate Detail	:		
Certificate Date:			
Appointed Qu	alified Inspector/TD	I Inspector:	
New New	(Entire Building)	June 9, 2016	Appointed Qualified Inspector
Location of Pr	operty to be Insure	d:	
Street:			
Lot:			
Block: Tr	act or Addition:		
1288 BELLA LU	JNA LANE		
City:			
County:			
State:			
LEAGUE CITY	GALVESTON	TEXAS	
Inside City Limi	ts Inland I - Inla	and I - International	Residential Code, 2006 Edition (Amended with 2006 Texas
Revisions)			

This Certificate of Compliance, Form WPI-8, is issued by the Texas Department of Insurance under Insurance Code § 2210.251 and § 2210.2515 and demonstrates that the improvement identified in the certificate complies with the applicable windstorm building code under 28 Texas Administrative Code §§ 5.4007 – 5.4011.