

## SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which

exceed the minimum this	iosures rec	L	rea by	/ the	code.							
CONCERNING THE P	ROPERT	Υ	AT 52	218 1	Rutherglenn Drive, Ho	usto	n, 1	X 77	096			-
THIS NOTICE IS A DI AS OF THE DATE S WARRANTIES THE B SELLER'S AGENTS, (	SIGNED I	BY AY	SE WIS	LLE H T	R AND IS NOT O OBTAIN. IT IS	A :	SU	BST	ITUTE FOR A	NY INSPECTION	ONS	OR
Seller is is not the Property?	occupyi /97/	ng	the	Pro	perty. If unoccupie (a	ed (	by rox	Sell- imat	er), how long si te date) or	ince Seller has never occu	occup pied	oied the
Section 1. The Prope This notice does not es	erty has t stablish the	he ite	item ems t	is n o be	narked below: (Me conveyed. The con	ark trac	Ye t w	es (Y ill de	/), No (N), or U termine which ite	nknown (U).) ms will & will not	conve	y.
Item	YNU	and a second	Iten	1		Y	N	/U	Item		Y	N U
Cable TV Wiring		down	Liqu	id F	Propane Gas:		V		Pump: 🗆 su	mp  grinder		
Carbon Monoxide Det.		udenamuna			mmunity (Captive)			De l				
Ceiling Fans		dissipations							Range/Stove		1	
Cooktop	00,0	edeminois	-LP on Property Hot Tub				V		Roof/Attic Ve			
Dishwasher		oukuspeani	Intercom System					一		3110		
Disposal		- Annual Contract of the Contr	Microwave				1	EV	Smoke Dete	ctor		
Emergency Escape Ladder(s)		n de la companyamente	Outdoor Grill							ctor – Hearing		20
Exhaust Fans	000	designation	Pati	o/D	ecking					The second secon		
Fences	doo	1	Plur	nbir	ng System			V	Trash Comp	actor		
Fire Detection Equip.			Pool						TV Antenna			
French Drain			Poo	IEC	juipment				Washer/Drye	er Hookun		
Gas Fixtures	000	adcament			aint. Accessories				Window Scre			
Natural Gas Lines	□ □ □ Pool Heater				₩Z	1	Public Sewe					
		Ł				1	1 -0-		1 40110 00110	· Oyotom	Acri L	
Item		Y	N	U	Addition	al	nf	orma	ation			
			☑ □ □ ☑ electric □ gas number of units:									
Evaporative Coolers			D D number of units: SNE									
Wall/Window AC Units			□ \□ number of units:									
Attic Fan(s)			Z D D if yes, describe: DART OF GUNLAN									
Central Heat			□ □ □ delectric □ gas number of units:									
Other Heat			□ □ if ves describe:									
Oven			□ □ number of ovens: ON E □ electric □ gas □ other:									
			☐ ☐ ☐ wood ☐ gas logs ☐ mock ☐ other:									
			☐ attached ☐ no									
			number of units:				number of rem	otes:				
			□ owned □ leas	ed	fro	*						
Security System												
Solar Panels												
Water Heater ☐ ☐ ☐ delectric ☐ gas												
and any and oncount of gue					□ owned □ leas							
Other Leased Item(s)		Ē			if yes, describe:	Ju	110	.11				
(TXR-1406) 07-08-22	Initial		by: B			nd S	Selle	er.	56	Pa	ge 1 o	f 6

Concerning the Property at 5218 Rutherglenn Drive, Ho	ousto	n, TX	77096					
Underground Lawn Sprinkler						414		
Septic / On-Site Sewer Facility   D   D   T	aut	omati	c $\square$ ma	nual	areas covered	d:_	-	
							(R-1	407
Water supply provided by: ☐ city ☐ well ☐ Was the Property built before 10793. ☐	MU	D $\square$	co-op [	Junkn	own 🛮 other			
The state of the s	Inc	1 1	introuser					
(If yes, complete, sign, and attach TXR-19)	06 c	oncer	ning lead	d-base	d paint hazard	ls).		
Roof Type: Slato Slato Slato Start S		Ag	e:			(annr	vim	ata)
is there an overlay root covering on the Prope	rty (s	shing	les or roc	of cove	ring placed ov	er existing shing	26 0	r roc
O/ - /								
Are you (Seller) aware of any of the items list defects, or are need of repair? If yes, I no	tod i	in this	Cootion	4 41				
defects, or are need of repair? Tyes I no	If vo	u u u	o Section	i inai	are not in we	orking condition,	that	have
Stave top PAHAMST FA	11 70	3, ue	scribe (a	mach a	aditional shee	ets if necessary):_		
From Burner 1) ward	1	10.	1	VOR	12109			
Stave top Ethaws T FA	10	6	e Li	+ 1	ox ma	Tell		
Section 2. Are you (Seller) aware of any de if you are aware and No (N) if you are not av	ereci	s or	maltunc	tions i	n any of the f	following? (Marl	(Ye	s (Y
(it) ii you did not di	ware	:-)						
Item Y N, Item			Y	N	Item		120	
Basement   Floors				M	Sidewalks		Y	
Ceilings	I/SI	ab(s)			Walls / Fend	200	-	
Doors   D   Interior Wa		(0)			Windows	,62		-
Driveways		S		Ø,				-
Electrical Systems					Other Struct	ural Components		-
Exterior Walls   Roof	9010	7110						
If the answer to any of the items in Section 2 is	yes,	, expl	ain (attac	ch addi	tional sheets i	f necessary):		
								-
Soction 2 American								
Section 3. Are you (Seller) aware of any o	f the	e foll	owing co	onditio	ons? (Mark )	res (Y) if you are	e av	vare
Section 3. Are you (Seller) aware of any o and No (N) if you are not aware.)	f the	e foll	owing co	onditio	ons? (Mark )	res (Y) if you are	e av	vare
Section 3. Are you (Seller) aware of any o and No (N) if you are not aware.)  Condition					ons? (Mark )	es (Y) if you are	e av	vare
Condition	Υ	N	Condi	tion	ons? (Mark )	res (Y) if you are		
Condition Aluminum Wiring	Y	N	<b>Condi</b> Radon	tion Gas	ons? (Mark )	res (Y) if you are		N
Condition Aluminum Wiring Asbestos Components	Y	N	Condi Radon Settlin	tion Gas		res (Y) if you are	Υ	N
Condition Aluminum Wiring Asbestos Components Diseased Trees: □ oak wilt □	<b>Y</b>	N	Condi Radon Settling Soil Mo	tion Gas g	nt		Y	N
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property	Y	NONDA	Condi Radon Settling Soil Me Subsu	tion Gas g overne	nt Structure or Pit	SS	Y	N
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines	Y	D D D D D D D	Condi Radon Settling Soil Me Subsul Underg	tion Gas g overne rface S ground	nt Structure or Pit Storage Tank	SS	Y	N
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste	Y	D D D D D D D	Condi Radon Settling Soil Me Subsul Underg Unplat	tion Gas g overne rface S ground ted Eas	nt Structure or Pit Storage Tank sements	SS	Y	N
Condition  Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage	Y		Condi Radon Settling Soil Me Subsur Underg Unplate Unreco	tion Gas g overne rface S ground ted Eas	nt Structure or Pit Storage Tank sements	is s	Y	A D D D D D D D D D D D D D D D D D D D
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs	Y		Condi Radon Settling Soil Me Subsui Underg Unplate Unreco	tion Gas g overne rface S ground ted Eas	nt Structure or Pit Storage Tank sements asements ehyde Insulati	is s	Y	D B B B B B B B B B B B B B B B B B B B
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill	Y		Condi Radon Settling Soil Me Subsui Underg Unplate Unreco	tion Gas g overne rface S ground ted Eas	nt Structure or Pit Storage Tank sements asements ehyde Insulati	is s	Y	BURDADARA
Condition  Aluminum Wiring  Asbestos Components  Diseased Trees: ☐ oak wilt ☐  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Improper Drainage  Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards	Y		Condi Radon Settling Soil Me Subsur Underg Unplate Unreco Urea-fo Water	tion Gas g overne rface S ground ted Eas orded E ormald Damag	nt Structure or Pit Storage Tank sements asements ehyde Insulati	is s	Y	
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property	Y		Condi Radon Settling Soil Me Subsur Underg Unplate Unreco Urea-fo Water	tion Gas g overne rface S ground ted Eas orded E ormald Damag	nt Structure or Pit Storage Tank sements asements ehyde Insulati	is s	Y	
Condition  Aluminum Wiring  Asbestos Components  Diseased Trees: ☐ oak wilt ☐  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Improper Drainage  Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards	Y		Condi Radon Settling Soil Me Subsur Underg Unplate Unread Uread Water Wetlan	tion Gas g overne rface S ground ted Eas orded E ormald Damag	nt Structure or Pit Storage Tank sements asements ehyde Insulati ge Not Due to	on a Flood Event	Y	
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property	Y		Condi Radon Settling Soil Mo Subsui Underd Unplate Unreco Urea-fo Water Wetlan Wood I Active	governe rface S ground ted Eas orded E ormalde Damag ids on I Rot infesta	nt Structure or Pit Storage Tank sements asements ehyde Insulati ge Not Due to Property	is s	Y	
Condition  Aluminum Wiring  Asbestos Components  Diseased Trees: ☐ oak wilt ☐  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Improper Drainage  Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in Historic District	Y		Condi Radon Settling Soil Me Subsul Underg Unplate Unrecc Urea-fo Water Wetlan Wood I Active destroy	tion Gas g overne rface S ground ted Eas orded E ormald Damag ds on I Rot infesta	nt Structure or Pit Storage Tank sements asements ehyde Insulati ge Not Due to Property tion of termite sects (WDI)	on a Flood Event es or other wood	Y	
Condition  Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation	Y		Condi Radon Settling Soil Me Subsul Underg Unplate Unreco Urea-fo Water Wetlan Wood I Active destroy Previou	tion Gas g overne rface S ground ted Eas orded E ormald Damag ds on I Rot infesta ving ins	nt Storage Tank sements asements ehyde Insulati ge Not Due to Property tion of termite sects (WDI)	on a Flood Event es or other wood	Y	T S RECENERATE RES
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs	Y		Condi Radon Settling Soil Me Subsui Underd Unplate Unrea-fe Water Wetlan Wood I Active destroy Previou	governed Face Spround ted East orded East or	nt Structure or Pit Storage Tank sements asements ehyde Insulati ge Not Due to Property tion of termite sects (WDI) tment for term ite or WDI day	on a Flood Event es or other wood		
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs	Y	GAR PURRUMENTERS	Condi Radon Settling Soil Me Subsui Underd Unreco Urea-fo Water Wetlan Wood I Active destroy Previou Previou Previou	governer face Stormalder Damage in stream is Fires	nt Structure or Pit Storage Tank sements asements ehyde Insulati ge Not Due to Property tion of termite sects (WDI) ment for term ite or WDI dan	on a Flood Event es or other wood ites or WDI mage repaired	Y 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs	Y		Condi Radon Settling Soil Me Subsur Underg Unplate Unreco Urea-fo Water Wetlan Wood I Active destroy Previou Previou Termite	tion Gas g overne rface S ground ted Eas orded E ormald Damag ds on l Rot infesta ving ins us treat us term us Fires	nt Structure or Pit Storage Tank sements sements ehyde Insulati ge Not Due to Property tion of termite sects (WDI) ment for term ite or WDI dan S DI damage ne	on a Flood Event es or other wood ites or WDI mage repaired		
Condition  Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Other Structural Repairs	Y		Condi Radon Settling Soil Mi Subsui Underg Unplate Unrea-fo Water Wetlan Wood I Active destroy Previou Previou Termite Single	tion Gas g overne rface S ground ted Eas orded E ormald Damag ds on I Rot infesta ving ins us treat us term us Fires or WE Blocka	nt Structure or Pit Storage Tank sements sements ehyde Insulati ge Not Due to Property tion of termite sects (WDI) ment for term ite or WDI dan S DI damage ne	on a Flood Event es or other wood ites or WDI mage repaired	Y	ANDREA O NEORNANDRAS
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture	Y	GAR PURRUMENTERS	Condi Radon Settling Soil Me Subsur Underg Unplate Unreco Urea-fo Water Wetlan Wood I Active destroy Previou Previou Termite	tion Gas g overne rface S ground ted Eas orded E ormald Damag ds on I Rot infesta ving ins us treat us term us Fires or WE Blocka	nt Structure or Pit Storage Tank sements sements ehyde Insulati ge Not Due to Property tion of termite sects (WDI) ment for term ite or WDI dan S DI damage ne	on a Flood Event es or other wood ites or WDI mage repaired	Y 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ANDREA O NEORNANDRAS
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs	Y	A REGIS PURRUNCEPRURA	Condi Radon Settling Soil Mi Subsui Underg Unplate Unrea-fo Water Wetlan Wood I Active destroy Previou Previou Termite Single	tion Gas g overne rface S ground ted Eas orded E ormald Damag ds on I Rot infesta ving ins us treat us term us Fires or WE Blocka	nt Structure or Pit Storage Tank sements sements ehyde Insulati ge Not Due to Property tion of termite sects (WDI) ment for term ite or WDI dan S DI damage ne	on a Flood Event es or other wood ites or WDI mage repaired	Y	ANDREA O NEORNANDRAS
Condition Aluminum Wiring Asbestos Components Diseased Trees: ☐ oak wilt ☐ Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture	Y		Condi Radon Settling Soil Mi Subsui Underg Unplate Unrea-fo Water Wetlan Wood I Active destroy Previou Previou Termite Single	tion Gas G Overne rface S Ground ted Eas Orded E Ormald Damag ds on I Rot infesta ving ins us treat us term us Fires or WE Blocka a*	nt Structure or Pit Storage Tank sements sements ehyde Insulati ge Not Due to Property tion of termite sects (WDI) ment for term ite or WDI dan S DI damage ne	on a Flood Event es or other wood ites or WDI mage repaired	Y	ANDREA O NEORNANDRAS

Concerning the Property at 5218 Rutherglenn Drive, Houston, TX 77096						
If the answer to any of the items in Section 3 is yes, explain (attach additional sheets if necessary):						
*A single blockable main drain may cause a suction entrapment hazard for an individual.						
Section 4. Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair, which has not been previously disclosed in this notice?   yes In no If yes, explain (attach additional sheets if necessary):						
Section 5. Are you (Seller) aware of any of the following conditions?* (Mark Yes (Y) if you are aware and check wholly or partly as applicable. Mark No (N) if you are not aware.)						
Y, N Present flood insurance coverage.						
Previous flooding due to a failure or breach of a reservoir or a controlled or emergency release of water from a reservoir.						
☐ ☑ Previous flooding due to a natural flood event.						
Previous water penetration into a structure on the Property due to a natural flood.						
Located wholly partly in a 100-year floodplain (Special Flood Hazard Area-Zone A, V, A99, AE, AO, AH, VE, or AR).						
Located wholly partly in a 500-year floodplain (Moderate Flood Hazard Area-Zone X (shaded)).						
Located wholly partly in a floodway.						
☐ ☐ Located ☐ wholly ☐ partly in a flood pool.						
☐ ☐ Located ☐ wholly ☐ partly in a reservoir.						
If the answer to any of the above is yes, explain (attach additional sheets as necessary):						
*If Buyer is concerned about these matters, Buyer may consult Information About Flood Hazards (TXR 1414).						
For purposes of this notice:  "100-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a special flood hazard area, which is designated as Zone A, V, A99, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding, which is considered to be a high risk of flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.						
"500-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area, which is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding,						
"Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of Engineers.						
"Flood insurance rate map" means the most recent flood hazard map published by the Federal Emergency Management Agency under the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seq.).						
"Floodway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of a river or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as a 100-year flood, without cumulatively increasing the water surface elevation more than a designated height.						
"Reservoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retain water or delay the runoff of water in a designated surface area of land.						
(TXR-1406) 07-08-22						

ind Selier: Page 3 of 6

Concerning the Property at 5218 Rutherglenn Drive, Houston, TX 77096						
	on 6. Have you (Seller) ever filed a claim for flood damage to the Property with any insurance ler, including the National Flood Insurance Program (NFIP)?*  yes one if yes, explain (attach nal sheets as necessary):					
risk stru	mes in high risk flood zones with mortgages from federally regulated or insured lenders are required to have flood insurance. In when not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate and low risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the cture(s).					
	n 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Business istration (SBA) for flood damage to the Property?   yes property on the U.S. Small Business is tration (SBA) for flood damage to the Property?  yes property on the U.S. Small Business is trational as necessary):					
Section if you a	n 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.)					
Y N/	Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time.					
	Homeowners' associations or maintenance fees or assessments. If yes, complete the following:  Name of association:    Note					
	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following:  Any optional user fees for common facilities charged?   yes  no If yes, describe:					
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.					
	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)					
	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.					
	Any condition on the Property which materially affects the health or safety of an individual.					
	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).					
	Any rainwater harvesting system located on the Property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.					
	Any portion of the Property that is located in a groundwater conservation district or a subsidence district.					
If the answer to any of the items in Section 8 is yes, explain (attach additional sheets if necessary):						
(TXR-1406	6) 07-08-22 Initialed by: Buyer: and Seller: 66					

Concerning the Plop	erty at 5218 Ruther	rglenn Drive, Houston, T	TX 77096		
Section 9. With persons who re permitted by law	nin the last 4 egularly provid v to perform ins	years, have you ( le inspections and spections? □ yes	Seller) rec who are o	eived any written either licensed as , attach copies and	inspection reports from inspectors or otherwise complete the following:
Inspection Date	Туре	Name of Inspe	ector		No. of Pages
Note: A buyer sh	ould not rely on A buyer shou	the above-cited repo ld obtain inspections	orts as a rei	flection of the curren	at condition of the Property.
☐ Wildlife Mar ☐ Other:	ck any tax exer	nption(s) which you ☑ Senior Citizen ☑ Agricultural	u (Seller) cı	urrently claim for to Disabled Disabled Vetera Unknown	he Property:
Section 11. Have with any insuran	you (Seller) e	ever filed a claim for	or damage,	other than flood	damage, to the Property
Section 12. Have	Vou (Seller)	OVAT received	ceeds for	a claim for dama	ge to the Property (for
		ne claim was made?			
or unknown, expla	in. (Attach add	itional sheets if nece	bke detecto h and Safer ssary):	rs installed in acc by Code?* □ unkno	ordance, with the smoke own ☑ no ☐ yes. If no
including perform	ance, location, and	fety Code requires one-f quirements of the buildir power source requireme n above or contact your l	ng code in en	ect in the area in whic	working smoke detectors h the dwelling is located, ode requirements in effect
A buyer may requestion family who will re- impairment from a seller to install sn	uire a seller to insta eside in the dwelli a licensed physician noke detectors for	all smoke detectors for the ng is hearing-impaired;	ne hearing imp (2) the buyer after the effect	eaired if: (1) the buyer or gives the seller written ive date, the buyer make	r a member of the buyer's n evidence of the hearing es a written request for the
Seller acknowledge	es that the state	ments in this notice	ara tmia ta	4b	belief and that no person, formation or to omit any
Shaw Signature of Seller	Erch	10/13/23 Date	Signatu	re of Seller	Date
Printed Name: Share	on Eickmann	=	Printed	Name:	23.0
TXR-1406) 07-08-22	Initialed I	py: Buyer:	and Sel		Page 5 of 6

## ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review Information Regarding Windstorm and Hail Insurance for Certain Properties (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported info

media independently incustrica to verify any reported	monnation.
(6) The following providers currently provide service to th	e Property:
Electric: RELANT	phone #: 1- 8877. RET PAID
Sewer: City of Houston	phone #: 7/3-37/-/400
Water: City of Hous you	phone #: 7/3 ~ 37/ -/400
Cable: DISCONTIDUEL X FINITY	phone #:
Trash: City of Houston	phone #:
Natural Gas: CENTER POINT ENERCY	phone #:
Phone Company:	phone #:
Propane:	phone #:
Internet:	phone #:
(7) This Seller's Disclosure Notice was completed by Sel this notice as true and correct and have no reason ENCOURAGED TO HAVE AN INSPECTOR OF YOU	ler as of the date signed. The brokers have relied on
The undersigned Buyer acknowledges receipt of the foregoing	going notice.
Signature of Buyer Date	Signature of Buyer Date
Printed Name:	Printed Name:
(TXR-1406) 07-08-22 Initialed by: Buyer:	and Seller: Page 6 of 6