

SURVEY MAP SHOWING BOUNDARIES AND IMPROVEMENTS ON LOT 17 AND THE WEST HALF OF LOT 16, BLOCK 3, GLENNVIEW SUBDIVISION ACCORDING TO THE PLAT AS RECORDED IN VOLUME 8, PAGE 66, PLAT RECORDS, BRAZORIA COUNTY, TEXAS.

This survey was made on the ground on March 3, 2017 under my supervision, and conforms to the Texas Professional Land Surveying Practices Act and the General Rules of Procedures and Practices of the Texas Board of Professional Land Surveying.

Chad A. Gormly, Registered Professional Land Surveyor No. 5796
Gormly Surveying, Inc. FIRM# 10095700
P. O. Box 862, Alvin, Texas 77512-0862 Phone (281) 331-0883

SOURCE OF BEARING BASED UPON THE TEXAS COORDINATE SYSTEM, SOUTH CENTRAL ZONE (4204), NAD 83(NA2011) AS COMPUTED FROM THE LEICA TEXAS SMARTNET RTK GPS NETWORK.

THE NORTH LINE OF MEADOWVIEW DRIVE WAS HELD FOR DIRECTIONAL CONTROL.

Chad A. Gormly has not performed an Abstract of Title on the above surveyed property.

This survey performed without the benefit of a title commitment or report at the request and direction of Mr. Billy Threadgill for the purposes of pool construction.

STATE OF TEXAS REGISTERED CHAD A. GORMLY 5796 PROFESSIONAL LAND SURVEYOR

J07-

BK. 2016-1, PG. 51

DocuSign Envelope ID: C897911A-F37E-4A1D-8A78-223CAE12E02D