7619 Magnolia Shadows Improvements

- New electrical breaker box installed July 2014
- Added covered patio with stamped concrete August 2016
- Replaced windows on North and East sides November 2020
- Replaced HVAC and A/C February 2020
- Smoke detectors installed in all bedrooms Fall 2021
- Replaced siding on North and West sides March 2022
- Replaced all gutters and downspouts March 2022
- Painted exterior March 2022
- New garbage disposal February 2023
- Painted interior March 2023
- Rebuilt underground sprinkler system March 2023
- New landscaping March 2023