

Items we are aware are in need of repairs and are in the process of repairing:

- a) Stair bullnose/edges - various
- b) Glass panel on third floor balcony - cracked, pending replacement
- c) Mismatched tile in kitchen - pending replacement
- d) Bath fan in primary bathroom - pending replacement
- e) Access panel in first floor bedroom - pending installation