

5953 Nunn St. STE. B Houston, TX. 77087 Fax: 713-242-7985

Nancy Tevo 13550 Quetzal Lane Houston, Texas 77083

A test was done on the entire system after repairs were made. The test was held at 100% over a thirty minute period. No leaks were present at the time.

Reny Plumbing