


J R Foundation Repair

Invoice To: John Martin 309 E Foley St Alvin, TX 77511

Date	Order No.	Sales Rep.	Type of Work	
07/10/23	190	Harvin Jimenez	Foundation repair	

Quantity	Item	Description	Material	Total
		Foundation Repair House leveling 20 piers		\$4,975

TOTAL: \$4,975



J R Foundation Repair has installed \(\frac{1}{2}\) exterior and interior driven concrete piers at the structure located at \(\frac{309 \text{ E-foley AUNTE-175||}}{200 \text{ E-foley AUNTE-175||}}\). See pier layout provided hereto.

Life Time Warranty may be transferred to new owner, for a transfer fee of \$300 payable to J R Foundation Repair within the first 90 after property is granted, sold or conveyed to new owner.

J R Foundation Repair is only responsible for the foundation. Other areas of the property structure, both interior and exterior, are not covered under this warranty.

Any re-adjustment needed to the same piers installed by J R Foundation Repair will be performed at no additional cost for the life of this warranty, provided no other major structural changes have been made by the property's owner.

Service agreement effective: 07-10-23

J R Foundation Repair

Lazaro Jimenez 713.505.2387 www.jrfoundationrepair.com Member of the BBB Accredited since 3/17/2017 In business since March, 2012



HOUSE LEVELING & EVALUATION SERVICES
TRUSTED FOUNDATION REPAIR
ANDRE WELLS

281.797.9418 WWW.LEVL.ME

NAME JOHN MARTIN

ADDRESS 309 E FOLEY

ALVIN 77511


TEL 281 787 7830

EMAIL CAIDENCE 29 & GMAIL. COM

DATE JUNE 13, 2023

11 Ext. Piers 9 Interior Piers

Estimated Total: \$ 4975.



Price reflects a 3% discount for cash or check Elevation figures in inch tenths from reference point RP

EXT 11 9 TOT 20

BREAKOUTS 10

BUILDING DESCRIPTION
STORY 1
BRICK yes
PIER & BEAM

Andre Wells - Owner

LEGEND

- O EXTERIOR PILINGS
- INTERIOR PILINGS

W WALL CRACKS

X PREVIOUS WORK

- (A/C) A/C UNIT G GAS LINE
- UNSQUARE DOOR
 → SLOPE