MAC'S SEPTICS AND ROADS

P.O.BOX 163 DODGE, TX 77334 / 141 UTLEY RD. HUNTSVILLE, TX 77320

(936)581-1714

Sample Testing and Reporting Record (30 TAC 285)

his testing and reporting record will be completed, signed, and dated after each maintenance check and test. One copy will be given to the stem owner, one copy sent to the local permitting authority, and one copy retained by the maintenance provider.

	Inspection # $1/3$	Actual	Date of test	0-02-23		
2.	System Inspection:	system Inspection:				
	Property Address: 215 Frank Cloud Rd. Huntsville, TX 77.320					
	ermit Number: 2014 - 0172					
	Inspector: MAC LOUTHER	spector: MAC LOUTHER Signature: #MP00020				
	ITEMS INSPECTED	OPERA	TIONAL	INOPERATIVE		
ſ	Aerators	OTENA	HORAL	HOTEKATIVE		
1	Filters	1 close	in A Aid			
	Irrigation Pumps	Y CIEPIA	PC AIR			
-	Recirculation Pumps	1/			0	
1	Sludge Condition	10110	521 1	1	6	
ı	Disinfection Device	Schercls All working properly				
1	Chlorine Supply					
1	Electrical Circuits					
	Distribution system					
	Sprayfield Vegetation					
	Other as Noted:					
					Consession of the	
3.	Repairs to system: YES	(see attached report):		7		
4.		er maintenance inspection	n activities were	complete? YES NO		
	If no, explain				THE COURSE OF	
5.	Tests Required and Resul		A Marie San Marie			
Г	Tests	Required	Result	Test Method		
1	BOD (GRAB)	YES/NO				
1	TSS (GRAB)	YES/NO		(DDD) 107#		
+	CL2 (GRAB)	YES/NO	021	(DPD)- LOT #		
+	FECAL	YES/NO				
1	COLIFORM	YES/NO				
۔ ا	PH Data(s) responded to any	YES/NO		**************************************		
6.	Date(s) responded to ow	ner complaints during rep	porting period (a	ttach copy of Complaint and Fi	ndings Report)	
		- A ol	15 110			
7.	General Comments:	Sych work				
7.		this report and understan	nd that any main	tenance and/or repairs needed	d are my (the	
7.			nd that any main	tenance and/or repairs needed	d are my (the	