

I -69 SEPTIC PLUMBING SOLUTIONS LLC

12490 Hwy 59 South

Shepherd, TX 7737

Alarmsoff@gmail.com

281-223-0034

AUG 30, 2023

TAURINO MENDOZA

19239 HWY 321

CLEVELAND, TX 77327

713-825-0148

INSPECTION DATE: AUG 30, 2023

PROPERTY LOCATION: 19239 HWY 321. CLEVELAND TX 77327

SEPTIC INSPECTION REPORT

I - 69 SEPTIC PLUMBING SOLUTIONS LLC CONDUCTED A FUNCTIONAL FLOW TEST OF THE SEPTIC SYSTEM AT THE ABOVE-CITED PROPERTY TO DETERMINE THE FUNCTIONAL CONDITION OF THE SYSTEM. THE GENERAL AREA OF THE LEACHING FIELD WAS EXAMINED FOR THE EVIDENCE OF ODOR, WETNESS, AND OTHER INDICATIONS OF THE SYSTEM FAILURE. NONE WERE FOUND AT THE TIME OF INSPECTION.

THIS IS AN CONVENTIONAL SYSTEM, AND IS AN NON- PERMITTED SYSTEM, I PUT 380 GALLONS OF WATER INTO THE SYSTEM. MEETS HEALTH AUTHORITY APPROVAL STANDARDS. MAY NEED TO BE REPLACED IN THE FUTURE.

SINCERELY, DONNIE J REUM/ I-69 SEPTIC PLUMBING SOLUTIONS LLC. /
alarmsoff@gmail.com



T.C.E.Q CLASS II INSTALLER LIC: OS0022903
MAINTENANCE LIC: MP0001297
OSSF SITE SOIL EVALUATOR LIC: OS0033908

SIGNATURE: DONNIE REUM DATE: 08-30-23

DONNIE REUM *Donnie Reum* 8-30-23



Donnie Reum
8-30-23