CURVE DELTA ANGLE RADIUS ARC . TANGENT CHORD CHORD BEARING 4°45'12" 475.00 39.41 19.71 39.40 S 16°50'38"W Notes: Notes:

1. Basis of bearings: Recorded Plan.

2. Easements and building lines as shown are as recorded in Cabinet X. Sheet 20. MR.M.C.T. and as reflected on the recorded plan or as set forth in instruments recorded under CF No. 9348561 and CF No. 2004-139318. R.P.R.M.C.T.

3. Subject to access easement in favor of Villa Kaw Homeowners Association. Inc., as set forth in instrument recorded under CF No. 2006-110688. R.P.R.M.C.T.

4. Subject to access to be a vivided to the control of LINE BEARING DISTANCE N 20° 17'00 E 18.16 N 13°17'00'E L 2 17.69 This property lies within ZONE 'X' as SCALED from FEMA Map Panel Number 48339C0540H, dated August 18, 2014. THIS MEANS THAT THE SUBJECT PROPERTY SCALES OUTSDE THE 100 YEAR FLOOD PLAIN. 4. Subject to private utility easements in favor of VIIIa Row Homeowners Association, Inc., as set forth in instrument recorded under CF No. 2006-#1689. RPRMCT. This determination is made strictly occording to the FEMA Maps and does not reflect ectual on ground flood conditions. Furthermore, this company takes no responsibility for such. KMRM.C.I.

5. Subject to blanket easement over and across the subject property for ingress, egress, installation, examination, replacing, repairing, providing and maintaining all utilities servicing the property, as set forth in instrument recorded under CF No. 2006-III690, R.P.R.M.C.T.

6. Subject to easement over and across the publication of the property for ingress, and across the publication of the property for ingress, and across installation. Found 5/8" Iron Rod Controlling Manument 6. Subject to easement over and across the subject property for ingress and egress, installation, construction, replacing, repairing and maintaining access gate facility, as set farth in instrument recorded under CF No. 2006-10690, RPRM.C.T. 7, Subject to a 20 faot carport or garage selback when the carport or garage face is parallel to the street. The remainder of the structure shall be restricted to a 10 faot building line as per the recorded plat. recorded plat. Found Iron Rod 12 w/ Survey Cop 730 53·₄₅. Found Iron Rod , Concrete Driversoy w/ Survey Cop 130.06 of Lot Found Iron Rod Survey Cap Found Iron Rad 3 Story Stucco Residence Survey Cap ROW FF = 144.5 . 05 10 Found Iron Rod w/ Survey Cap Found Iron Rod w/ Survey Cap Controlling Monument Lot Eleven (11), in Block Two (2), of THE VILLAS, A PARTIAL REPLAT OF EAST SHORE, SEC. 3 RESERVES B AND H, a subdivision in Montgomery County, Texas, according to the map or plat thereof, recorded in Cabinet Z. Sheet 461 of the Map Records of Montgomery County, Texas.

Data June I. 2015	GF No 06404802 .
Job No 12-0500	Scale: 1" = 30"
Address 43 Olmstead Row	Drann By: 1
City, State Spring, Texas	Zp: 77380 Rev. 0

C & C Surveying, Inc.

7424 F.M. 1488, Suite A, Magnolia, Texas 77354 Office: 281-259-4377 Metro: 281-356-5172 Fax: 281-356-1935



Gertified To: Allen J. Tarbutton

Clent: Allen J. Tarbutton

I HEREBY CERTIFY THIS SURVEY WAS MADE ON THE CROWN, AND THAT THIS FLAT CHARGETLY REPRESENTS THE FACIS FOUND AT THE TIME OF SURVEY AND THAT THIS FROETESSIONAL SERVICE CONCERNS TO THE TEXAS SOCIETY OF PROFESSIONAL SURVEYORS STRUMPHON ON PERCHFLOATIONS FOR A CHECODY ME, CONCINCUL HIS SURVEY, AND THAT THERE ARE NO ENCORPOLITIONS EXCEPT AS SHOWN.

4

Sleven L Crews RPLS # 4141