PROPERTY ADDRESS: Creek Crossing Magnolia, TX 77355 7.6556 AC. 827 MAGNOLIA LTD LLP 2.6601 AC. MAGNOLIA CHURCH OF CHRIST BENSON SONES SURVEY A-541 FOUND 5/8" IRON ROD FOUND 5/8" N89° 56' 41"E 203.62' APPROX. SURVEY LINE CHRIS SHILLINGS SURVEY A-515 BLOCK (1) 7.6556 AC. 827 MAGNOLIA LTD LLP LOT 79 **LOT 78** 2.0758 Acres (90,421 Sq. Ft.) 3' X 35' G.E **EDWARD TAYLOR SURVEY** FOUND 5/8 A - 554CREEK CROSSING FOUND 5/8" IRON ROD FOUND 5/8" IRON ROD S89° 22' 41"W 250.00' (60' R.O.W.) APPROX. SURVEY LINE

SURVEY FOR: Vanguard Builders, Inc.

CHRIS SHILLINGS SURVEY

A-515

BEING: Lot 78, in Block 1, of MAGNOLIA CROSSING 2nd Replat, a subdivision in Montgomery County, Texas, according to the map or plat thereof, recorded in Cabinet C, Sheet 81A, of the Map Records of Montgomery County, Texas.

1. This survey was done without the benefit of a Title Report and only certifies to those building lines and easements shown on the recorded plat. 2. This Surveyor did not research the deed records for previous conflict in title or easement, therefore, certain easements may have been granted which are not reflected hereon.

3. B.L. = Building Line

4. U.E. = Utility Easement

5. D.E. = Drainage Easement

ROBINSON SURVEYING, INC.

16130 F.M. 943 LIVINGSTON, TEXAS 77351 PHONE (832) 236-8210 robinsonsurveyinginc@gmail.com



LOT 77

I, Thomas G. Robinson, certify that this survey was performed under my supervision on July 14, 2021; that there were no encroachments except as shown; that this survey conforms to T.S.P.S. Standards for a Category 1a, Condition III Survey; and that part of the subject property is in the 100 Year Flood Plain, and is in Zone "AE" on F.I.R.M. Map # 48339C 0480 G dated August 18, 2014. This certifies only to easements and building lines shown on the recorded plat.

Scale : 1" = 50'

Thomas G. Robinson, R.P.L.S. #1874