

## **SELLER'S DISCLOSURE NOTICE**

©Texas Association of REALTORS®, Inc. 2022

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

exceed the minimum disc	losı	ıres	s re	qui	red by	the	Code.								
CONCERNING THE PROPERTY AT 10407 Roseate Skimmer, Conroe, TX 77385															
THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE BUYER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER, SELLER'S AGENTS, OR ANY OTHER AGENT.															
the Property? $\square$ 12/31 Property	/202	3					(a	ppi	oxi	mat	te c	how long since Seller has date) or ☐ never occup			
												lo (N), or Unknown (U).) nine which items will & will not o	conv	⁄еу.	
Item	Υ	Ν	U		Item			Υ	N	U	It	tem	Υ	Ν	U
Cable TV Wiring	$\square$				Natu	ral (	Gas Lines	$\mathbf{V}$			F	Pump: sump grinder			
Carbon Monoxide Det.	$\square$				Fuel	Ga	s Piping:	abla			_	Rain Gutters	$\mathbf{\nabla}$		
Ceiling Fans	abla						on Pipe			$\square$	_	Range/Stove	$\checkmark$		
Cooktop	abla				-Cop							Roof/Attic Vents	abla		
Dishwasher						ruga	ated Stainless			☑		Sauna			
Disposal	$\square$				Hot 7		<b>9</b>		$\checkmark$		S	Smoke Detector	$\square$		
Emergency Escape Ladder(s)		Ø					System				S	Smoke Detector – Hearing mpaired			
Exhaust Fans	abla				Micro	owa	ve	$\square$				Spa		$\nabla$	
Fences	abla				Outd						_	rash Compactor			
Fire Detection Equip.	abla						ecking		1			√ Antenna		N	
French Drain	$\square$						g System	$\square$			_	Vasher/Dryer Hookup			
Gas Fixtures	$\square$				Pool		g e yete					Vindow Screens	$\nabla$		
Liquid Propane Gas:							uipment				_	Public Sewer System	abla	$\overline{\Box}$	$\bar{\Box}$
-LP Community		$\bigvee$	1				int. Accessories				<u> </u>	usiis seriei system			
(Captive)	ш	M						ш	M	Ш					
-LP on Property		$\bigvee$			Pool	He	ater		abla	П					
<u> </u>	<u> </u>			] [											
Item				Υ	N	U	Addition	al I	nfo	orm	atio	n			
Central A/C				V	1 🗆		☑ electric ☑ gas		nuı	mbe	er of	units: 2			
Evaporative Coolers				Г			number of units:								
Wall/Window AC Units	,			Ē			number of units:								
Attic Fan(s)					] 🛛		if yes, describe:								
Central Heat				V			☑ electric ☑ gas		nui	mbe	er of	units:2			
Other Heat				Ē			if yes describe:								
Oven				V		_	number of ovens:					electric □ gas □ other:			
Fireplace & Chimney				V				ogs	s E	] m					_
Carport															
Garage															
Garage Door Openers				V			number of units:					nber of remotes:			=
Satellite Dish & Control				V			☑ owned ☐ leas	ed	fro	m D		4			
Security System				V		_	☑ owned ☐ leas								
(TXR-1406) 07-10-23		li	nitia		by: Bu				Selle	▔	Ry 01/11/24 11:24 PM CS dotloop verifi	, <i>Dy</i>	ge 1	of 7	— 7
Bang Realty - Texas, Inc		114	<b>427</b> 1	Ree	d Hartm	ıan F	Iwy Ste 236 Cincinnati, C	H 4!	5241			888-737-2264 Daniel P	acut		

Water Softener																		
Water Softener		Solar Panels																
Other Leased Item(s)																		
Underground Lawn Sprinkler   D   D   D   D   D   D   D   D   D												ed :	fro	<u>m</u>	wa	ater filter and conditioner		
Septic / On-Site Sewer Facility			_															_
Water supply provided by: ☑ city ☐ well ☑ MUD ☐ co-op ☐ unknown ☐ other:  Was the Property built before 1978? ☐ yes ☑ no ☐ unknown  (If yes, complete, sign, and attach TXR-1906 concerning lead-based paint hazards).  Roof Type, Shingles  Roof Type, Shingles  Is there an overlay roof covering on the Property (shingles or roof covering placed over existing shingles or roof covering) ☐ yes ☑ no ☐ unknown  Are you (Seller) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, or are need of repair? ☐ yes ☑ no ☐ if yes, describe (attach additional sheets if necessary):  Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y if you are aware and No (N) if you are not aware.)  Item Y N Basement ☐ ☑ ☐ Interior Walls ☐ ☑ Interior																		
Was the Property built before 1978?	ļ	Septic / On-Site Sewer Facility		$\checkmark$		if	yes,	at	tach	1 Ir	nforn	na	tio	n A	b	out On-Site Sewer Facility (TX	R-14	07)
Item		Was the Property built before 19 (If yes, complete, sign, and a Roof Type: Shingles Is there an overlay roof covering covering)? ☐ yes ☑ no ☐ u	978′ attao g on nkno	? Ch The the own	ye XR Pr	s k-19 ope	☑ no 906 co erty (s	on Sh	□ this	unk nin e: <u>6</u> es	knowing leading to the second	n ad- irs oot	-ba f c	ase ove	ed eri	paint hazards). (approing placed over existing shingle	es or	roo
Basement										ma	alfur	nct	tio	ns	in	n any of the following? (Marl	Yes	s (Y
Ceilings	I	Item Y N		Iter	n						1	Y	N	1		Item	Y	N
Ceilings		Basement $\square$		Flo	ors								У	7		Sidewalks		$\nabla$
Doors		Ceilings □ ☑		Fou	unda	atio	on / S	la	b(s)			П	У	7		Walls / Fences		
Electrical Systems		Doors □ ☑		Inte	erio	r W	/alls					П	У	7		Windows		
Electrical Systems				Lig	htin	g F	ixture	es							Ī	Other Structural Components		abla
Roof				Plu	mbi	ing	Syste	en	ns				S		Ī			
Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition		Exterior Walls		Ro	of										Ī			
Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition		If the answer to any of the items	in '	200	tion	. 2	ie vas	•	ΔVN	اندا	n (at	tar	-h	2 d	dit	tional sheets if necessary):		
Condition		in the answer to any or the items	, III v	OCC	LIOI	_	is yes	,	СХР	ıaıı	ii (at	ıac	<i>)</i>	au	uit	tional sheets if fleeessary).		
Condition																		
Condition																		
Asbestos Components				re c	of a	ny	of th	ıe	fol	lov	wing	C	on	ndit	io	ons? (Mark Yes (Y) if you a	e av	vare
Asbestos Components	I	Condition					Y	,	N		Cor	ndi	itic	on			Y	N
Diseased Trees: □ oak wilt □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □		Aluminum Wiring						]	$\mathbf{V}$		Rad	dor	٦ (	Gas	;			abla
Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property Improvements encroaching on others' property  Located in Historic District  Historic Property Designation  Previous Foundation Repairs  Subsurface Structure or Pits  Underground Storage Tanks  Unplatted Easements  Unrecorded Easements  Urrea-formaldehyde Insulation  Water Damage Not Due to a Flood Event  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires  Page 2 of 7		Asbestos Components						]	$\square$		Set	tlin	ıg					$\bigvee$
Fault Lines       □ ☑       Underground Storage Tanks       □ ☑         Hazardous or Toxic Waste       □ ☑       Unplatted Easements       □ ☑         Improper Drainage       □ ☑       Unrecorded Easements       □ ☑         Intermittent or Weather Springs       □ ☑       Urea-formaldehyde Insulation       □ ☑         Landfill       □ ☑       Water Damage Not Due to a Flood Event       □ ☑         Lead-Based Paint or Lead-Based Pt. Hazards       □ ☑       Wetlands on Property       □ ☑         Encroachments onto the Property       □ ☑       Wood Rot       □ ☑         Improvements encroaching on others' property       □ ☑       Active infestation of termites or other wood destroying insects (WDI)       □ ☑         Located in Historic District       □ ☑       Previous treatment for termites or WDI       □ ☑         Historic Property Designation       □ ☑       Previous termite or WDI damage repaired       □ ☑         Previous Foundation Repairs       □ ☑       Previous Fires       □ ☑         (TXR-1406) 07-10-23       Initialed by: Buyer:       and Seller:       ☑       Page 2 of 7		Diseased Trees: ☐ oak wilt ☐ _						]	$\mathbf{V}$		Soil	M	lον	ven	ne	ent		$\bigvee$
Hazardous or Toxic Waste □ ☑ Unplatted Easements □ ☑ Unrecorded Easements □ ☑ Unrecorded Easements □ ☑ Urea-formaldehyde Insulation □ ☑ Urea-formaldehyde Insulation □ ☑ Water Damage Not Due to a Flood Event □ ☑ Encroachments onto the Property □ ☑ Wetlands on Property □ ☑ Wood Rot □ ☑ Active infestation of termites or other wood destroying insects (WDI) □ ☑ Historic Property Designation □ ☑ Previous treatment for termites or WDI □ ☑ Previous Foundation Repairs □ ☑ Previous Fires □ ☑ CTXR-1406) 07-10-23 Initialed by: Buyer: □ □ Initialed by:		Endangered Species/Habitat or	ı Pro	opei	rty			]	$\square$		Sub	วรเ	ırfa	ace	: S	Structure or Pits		abla
Improper Drainage       □ ☑       Unrecorded Easements       □ ☑         Intermittent or Weather Springs       □ ☑       Urea-formaldehyde Insulation       □ ☑         Landfill       □ ☑       Water Damage Not Due to a Flood Event       □ ☑         Lead-Based Paint or Lead-Based Pt. Hazards       □ ☑       Wetlands on Property       □ ☑         Encroachments onto the Property       □ ☑       Wood Rot       □ ☑         Improvements encroaching on others' property       □ ☑       Active infestation of termites or other wood destroying insects (WDI)       □ ☑         Located in Historic District       □ ☑       Previous treatment for termites or WDI damage repaired       □ ☑         Historic Property Designation       □ ☑       Previous Fires       □ ☑         Previous Fires       □ ☑         (TXR-1406) 07-10-23       Initialed by: Buyer:       and Seller:       ☑       Page 2 of 7													_			<u> </u>		
Intermittent or Weather Springs       □ ☑       Urea-formaldehyde Insulation       □ ☑         Landfill       □ ☑       Water Damage Not Due to a Flood Event       □ ☑         Lead-Based Paint or Lead-Based Pt. Hazards       □ ☑       Wetlands on Property       □ ☑         Encroachments onto the Property       □ ☑       Wood Rot       □ ☑         Improvements encroaching on others' property       □ ☑       Active infestation of termites or other wood destroying insects (WDI)       □ ☑         Located in Historic District       □ ☑       Previous treatment for termites or WDI       □ ☑         Historic Property Designation       □ ☑       Previous termite or WDI damage repaired       □ ☑         Previous Fires       □ ☑       Previous Fires       □ ☑         (TXR-1406) 07-10-23       Initialed by: Buyer:								_		_								
Landfill								_										
Lead-Based Paint or Lead-Based Pt. Hazards       □       ☑         Encroachments onto the Property       □       ☑         Improvements encroaching on others' property       □       ☑         Located in Historic District       □       ☑         Historic Property Designation       □       ☑         Previous Foundation Repairs       □       ☑         (TXR-1406) 07-10-23       Initialed by: Buyer:       □       ☑         Wetlands on Property       □       ☑         Active infestation of termites or other wood destroying insects (WDI)       □       ☑         Previous treatment for termites or WDI damage repaired       □       ☑         Previous Fires       □       ☑         (TXR-1406) 07-10-23       Initialed by: Buyer:       □       □         and Seller:       □       □       □         Instance       □       □       □         Previous Fires       □       □	Intermittent or Weather Springs																	_
Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs  Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires  □ ☑  (TXR-1406) 07-10-23 Initialed by: Buyer: □ ☑  and Seller: □ ☑  Page 2 of 7															_	•		
Improvements encroaching on others' property  Located in Historic District Historic Property Designation Previous Foundation Repairs  (TXR-1406) 07-10-23  Improvements encroaching on others' property  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires				t. H	aza	ard:				-					n	Property	_	_
Located in Historic District   □ □ □   Previous treatment for termites or WDI □ □ □ □   Previous treatment for termites or WDI □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □			_					J	V									abla
Located in Historic District Historic Property Designation Previous Foundation Repairs  TXR-1406) 07-10-23  Initialed by: Buyer:    Contact district   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for termites or WDI   Contact destroying insects (WDI)   Previous treatment for treatment for termites (WDI)   Previous treatment for treatment for treatment for treatme		Improvements encroaching on o	othe	rs' p	orop	ber	<sup>ty</sup>   ┌	1	$\square$								<sup>1</sup>   ¬	
Historic Property Designation ☐ ☐ ☐ Previous termite or WDI damage repaired ☐ ☐ ☐ Previous Foundation Repairs ☐ ☐ ☐ Previous Fires ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐		I handad in Distanta Di Ci C								-								
Previous Foundation Repairs □ ☑ Previous Fires □ ☑  (TXR-1406) 07-10-23 Initialed by: Buyer: □ and Seller: □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □								_		}								
(TXR-1406) 07-10-23 Initialed by: Buyer: and Seller: a								_		-								
0/11/124 0/11/124 11/24 PM.CST 11:34 PM.CST dotkop verified dotkop verified	١	•						<u> </u>	M	L	1				ıe			
		,		•	•	_	17 Cto 22	6.0	l	anc				٦	d	01/11/24 - 01/11/24 11/24 PM CST 11:24 PM CST dotloop verified dotloop verified		of 7

Concerning the Property at 10407 Roseate Skimmer, Conroe, TX 77385

Pre	evious	s Roof Repairs		$\square$	Termite or WDI damage needing repair □ ☑					
Previous Other Structural Repairs					Single Blockable Main Drain in Pool/Hot ☐ ☑ ☐ Industrial Industri					
		s Use of Premises for Manufacture amphetamine								
If th	ne an	swer to any of the items in Section 3 is y	es,	ехр	plain (attach additional sheets if necessary):					
<u> </u>		ngle blockable main drain may cause a suction e								
of	repai	ir, which has not been previously dis	clos	sed	ment, or system in or on the Property that is in need in this notice? □ yes □ no If yes, explain (attach					
		5. Are you (Seller) aware of any of th wholly or partly as applicable. Mark N			wing conditions?* (Mark Yes (Y) if you are aware and you are not aware.)					
<u>Y</u>	<u>N</u> ☑	Present flood insurance coverage.								
		Previous flooding due to a failure or water from a reservoir.	brea	ich (	of a reservoir or a controlled or emergency release of					
	abla	Previous flooding due to a natural flood	d eve	ent.						
	abla	Previous water penetration into a struc	ture	on t	the Property due to a natural flood.					
		Located □ wholly □ partly in a 100-ye AO, AH, VE, or AR).	ear 1	flood	dplain (Special Flood Hazard Area-Zone A, V, A99, AE,					
	abla	Located ☐ wholly ☐ partly in a 500-ye	ar fl	ood	Iplain (Moderate Flood Hazard Area-Zone X (shaded)).					
	$\checkmark$	Located ☐ wholly ☐ partly in a floodw	ay.							
	abla	Located ☐ wholly ☐ partly in a flood p	ool.							
	abla	Located ☐ wholly ☐ partly in a reserve	oir.							
If th	ne an	swer to any of the above is yes, explain		ach	additional sheets as necessary):					
		Buyer is concerned about these matters, E ourposes of this notice:	Buye	er ma	ay consult Information About Flood Hazards (TXR 1414).					
	"100 which	I-year floodplain" means any area of land that: (A n is designated as Zone A, V, A99, AE, AO, AH	, VE,	, or A	tified on the flood insurance rate map as a special flood hazard area, AR on the map; (B) has a one percent annual chance of flooding, include a regulatory floodway, flood pool, or reservoir.					
	area,				ntified on the flood insurance rate map as a moderate flood hazard nd (B) has a two-tenths of one percent annual chance of flooding,					
	"Flood pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that is subject to controlled inundation under the management of the United States Army Corps of Engineers.									

(TXR-1406) 07-10-23

Bang Realty - Texas, Inc

Initialed by: Buyer: and Seller:

71/11/24 11:24 PM CST dottoop verified 11:34 PM CST dottoop verified

Page 3 of 7

11427 Reed Hartman Hwy Ste 236 Cincinnati, OH 45241

888-737-2264

Daniel Pacut

"Flood insurance rate map" means the most recent flood hazard map published by the Federal Emergency Management Agency under the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seq.).

"Floodway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of a river or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as a 100-year flood, without cumulatively increasing the water surface elevation more than a designated height.

"Reservoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retain water or delay the runoff of water in a designated surface area of land.

provide	6. Have you (Seller) ever filed a claim for flood damage to the Property with any insurance er, including the National Flood Insurance Program (NFIP)?* ☐ yes ☑ no If yes, explain (attach nal sheets as necessary):
Ever risk, struc	nes in high risk flood zones with mortgages from federally regulated or insured lenders are required to have flood insurance.  In when not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate and low risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the sture(s).  In 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Business
Admini	stration (SBÁ) for flood damage to the Property?  yes  no If yes, explain (attach additional as necessary):
	n 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.)
<u>Y N</u> □ ☑	Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time.
	Homeowners' associations or maintenance fees or assessments. If yes, complete the following:  Name of association: Harpers Preserve CAI  Manager's name: Lead  Phone: 281-857-6027  Fees or assessments are: \$1821.5  per year  Any unpaid fees or assessment for the Property? ☐ yes (\$) ☑ no  If the Property is in more than one association, provide information about the other associations below or attach information to this notice.
	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following:  Any optional user fees for common facilities charged? □ yes ☑ no If yes, describe:
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)
	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.
	Any condition on the Property which materially affects the health or safety of an individual.
	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
	Any rainwater harvesting system located on the Property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.
•	Page 4 of 7
Dang Kea	lty - Texas, Inc 11427 Reed Hartman Hwy Ste 236 Cincinnati, OH 45241 888-737-2264 Daniel Pacut

Bang Realty - Texas, Inc

dotloop signature verification: dtlp.us/gTPV-1kvE-aGZI

11427 Reed Hartman Hwy Ste 236 Cincinnati, OH 45241

888-737-2264

**Daniel Pacut** 

Seller acknowledges that the statements in this notice are true to the best of Seller's belief and that no person, including the broker(s), has instructed or influenced Seller to provide inaccurate information or to omit any material information.

Robert Young	dotloop verified 01/11/24 11:24 PM CST ZNGW-SXRT-S66W-7JWV	Dasa Young	dotloop verified 01/11/24 11:34 PM CST 3786-X9TH-NHCQ-7ASS
Signature of Seller	Date	Signature of Seller	Date
Printed Name: Robert Young		Printed Name: Dasa Young	

## ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit <a href="https://publicsite.dps.texas.gov">https://publicsite.dps.texas.gov</a>. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.

Electric: Entergy	phone #:	
Sewer: <sub>Mud 95</sub>	phone #:	
Water: <sub>mud 95</sub>	phone #:	
Cable:	phone #:	
Trash: <sub>mud 95</sub>	phone #:	
Natural Gas:entergy	phone #:	
Phone Company:	phone #:	
Propane:	 phone #:	
Internet:consolidated	 phone #:	

(TXR-1406) 07-10-23

Initialed by: Buyer:

(6) The following providers currently provide service to the Property:

and Seller:

**DY** 01/11/24

Page 6 of 7

Bang Realty - Texas, Inc

11427 Reed Hartman Hwy Ste 236 Cincinnati, OH 45241

888-737-2264

Daniel Pacut

(7)	This	Seller	's Dis	closure	Notice	was o	complete	d by	Selle	r as	of the	date	sigr	ned.	The	broker	s ha	ve reli	ed on
` ,	this	notice	as tr	ue and	d correc	t and	have no	o rea	ason t	o be	elieve	it to	be '	false	or	inaccura	ate.	YOU	ARE
	ENC	COURA	AGED	TO HA	VE AN	INSPI	ECTOR (	OF Y	OUR	CHC	DICE I	NSPI	ECT	THE	PR	OPERT	Y.		

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name	

(TXR-1406) 07-10-23

Initialed by: Buyer:

and Seller:

Page 7 of 7

RY