**Property Condition Report** 

**Case Number:** 512-320087

20087 Contract Area: 2D

**Current Step:** 3a-Disposition Pending **Step Date:** 02/26/2024

Address: 3205 VINTAGE VIEW LN
City, St Zip: PEARLAND, TX 77584-0000

HOC: Denver

		Property Cor	ndition Repo	rt
Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-ConditioneHeating/Furnace:HVAC System Duct:	r: OK OK OK	HVAC tested and functional?:	Yes	Generator
Electrical Wiring:Other:Other:	ок ок ок	Electric supply tested and functional?:	Yes	Generator
Stove/Range/Oven:Kitchen Cabinets:Other:	OK OK Missing	Built-in appliances tested and functional?:	No	Appliances missing; could not test
Plumbing:Sink:Other:	OK OK OK	Water supply tested and functional?:	Yes	Pressure Test Pass
Water Heater:	ОК	Water heater functional?:	Yes	Water heater visually inspected pass
Sewer/Septic System:Toilet:Other:	ок ок ок	Sanitary & plumbing system functional?:	Yes	Pour Water/Antifreeze In Drains Pass
Roof: Other:	OK OK	Roofing in acceptable condition?:	Yes	Visual