

**All Around Electrical  
Service, LLC**

104 North Robb--PO  
Box 2774

TRINITY, TX 75862

(936)594-0621

Allaroundelectricservi  
ce@gmail.com



# INVOICE

**BILL TO**

Christopher Smith  
11411 HWY 94  
Trinity, TX 75862

**SHIP TO**

Christopher Smith  
11411 HWY 94  
Trinity, TX 75862

**INVOICE #** 10704

**DATE** 10/31/2023

**DUE DATE** 11/20/2023

**TERMS** Due on receipt

DATE	ACTIVITY
10/20/2023	<b>Generator Assessment</b> Generator Assessment 11411 HWY 94 Trinity TX 75862

The customer contacted our office on 10/03/23 and wanted an overall assessment of the generator. Karsten went by on 10/17/23 and found the unit to have alarms. Matt went back out on 10/20/23, replaced the battery and one terminal on the unit. He was able to clear the alarms and performed a successful transfer test.

It was noted that the unit did not have proper 3' clearance, however the unit was in working condition.

10/20/2023	<b>Material</b> Replacement battery
10/20/2023	<b>Fuel Surcharge 0 - 30 Miles</b> Fuel Surcharge 0 - 30 Miles- \$20.00

Thank you for your business! Please note that we no longer accept credit cards. Cash or check only! Sorry for the inconvenience!

SUBTOTAL	400.00
TAX	6.60
TOTAL	406.60
PAYMENT	406.60
BALANCE DUE	<b>\$0.00</b>

All Around Electrical  
Service, LLC  
104 North Robb--PO  
Box 2774  
TRINITY, TX 75862  
(936)594-0621  
Allaroundelectricservi  
ce@gmail.com



## INVOICE

**BILL TO**  
Christopher Smith  
11411 HWY 94  
Trinity, TX 75862

**SHIP TO**  
Christopher Smith  
11411 HWY 94  
Trinity, TX 75862

**INVOICE #** 10704  
**DATE** 10/31/2023  
**DUE DATE** 11/20/2023  
**TERMS** Due on receipt

DATE	ACTIVITY
10/20/2023	<b>Generator Assessment</b> Generator Assessment 11411 HWY 94 Trinity TX 75862

The customer contacted our office on 10/03/23 and wanted an overall assessment of the generator. Karsten went by on 10/17/23 and found the unit to have alarms. Matt went back out on 10/20/23, replaced the battery and one terminal on the unit. He was able to clear the alarms and performed a successful transfer test.

It was noted that the unit did not have proper 3' clearance, however the unit was in working condition.

10/20/2023	<b>Material</b> Replacement battery
10/20/2023	<b>Fuel Surcharge 0 - 30 Miles</b> Fuel Surcharge 0 - 30 Miles- \$20.00

Thank you for your business! Please note that we no longer accept credit cards. Cash or check only! Sorry for the inconvenience!

<b>SUBTOTAL</b>	400.00
<b>TAX</b>	6.60
<b>TOTAL</b>	406.60
<b>BALANCE DUE</b>	<b>\$406.60</b>