607 W POLK ST UNIT C HOME IMPROVEMENTS/UPDATES

Exterior:

Ring camera installation for front door, side backyard and backdoor

Shatter resistant 3M window film

- Installed 9/30/22
- Lifetime Product Warranty (Warranty ID # US-20221004-717943)

Artificial grass installment along backyard

- Synthetic Grass Pros installed 1/2021

Garage epoxy by Houston Garage Floors 5/2022

Exterior sealants redone to windows and surrounding home Re-routed gutter installation away from top terrace - 11/2023

Added proper relief installation, flashing for top terrace Added proper door pan for top terrace entry door New and properly slopped top terrace roof - ICE Stucco 2024

Interior:

Nest thermostat installed for all floors Light dimmer switches installed in living room, dining room, kitchen and master bedroom Modern chandelier for dining room Energy efficient Bosch appliances Double paned windows

Properly maintained:

Biannual AC & heater maintenance service check with Majestic AC - Recently replaced Turbo 200 Motor Run Capacitor 5/26/2023 for AC Annual water heater service + flush with Hot Water Guys