



**McGarrett AC & Heating**  
 12623 Arlington Meadows Ln.  
 Tomball, TX 77377  
 \* 346.946.7577  
 mcgarrettac@gmail.com  
 TACLB 27809E

**INVOICE 11895**

JOB LOCATION			JOB LOCATION	
NAME:	PHONE:		LABOR	MATERIALS/EQUIPMENT
STREET: 13600 BRETON RIDGE ST #17 B			1 YEAR	All materials, parts, & equipment are warranted by the manufacturers' or suppliers' written warranty only.
CITY: HOUSTON	STATE: TX	ZIP: 77070	MATERIALS / EQUIPMENT CONDENSER	
BILL TO (IF DIFFERENT FROM LOCATION)			UNIT: <input checked="" type="checkbox"/> INDOOR <input type="checkbox"/> OUTDOOR	UNIT: <input type="checkbox"/> INDOOR <input checked="" type="checkbox"/> OUTDOOR
NAME: BRETT STANAKER	PHONE: 832-257-2428		MAKE GOODMAN	MAKE GOODMAN
STREET:			MODEL CHPF2430B/A	MODEL GSXM403010AA
CITY:	STATE:	ZIP:	SERIAL # 1905125274	SERIAL # 2311140950

PAYMENT METHOD		
<input type="checkbox"/> CASH	<input type="checkbox"/> CHECK	<input type="checkbox"/> CREDIT CARD
<input type="checkbox"/> VENMO	<input type="checkbox"/> ZELLE	

SERVICE REQUESTED			
A/C & HEAT INSPECTION FOR SALE FURNACE LENNOX			
MOD # G40UH-36A-070-15			
SER # 5910F12761			

DESCRIPTION OF WORK PERFORMED		ITEM	QTY	AMOUNT
DATE: 10-25-24	TECH 1: JACOB	INSPECTION		\$ 90.00
IN: 10:25	OUT: 11:15			\$
<p>I checked out all A/C + heating systems. The outside is a 2023 3.5 TON GOODMAN condenser, evaporator is a 2019 2.5 to 3 TON Box coil, furnace is a 2010 Lennox gas furnace. All are in good shape and working fine. I started up the furnace and the a/c. The a/c has a 20° drop across the coil. Water heater looks to be in good condition.</p>				\$
				\$
				\$
				\$
				\$
				\$
				\$
				\$
				\$
				\$

I, customer, or agent for the owner(s) have authority to order and/or approve the above work to be performed. McGarrett AC & Heating is authorized to do the work specified. I agree to pay for the above labor, material, and equipment charges per the terms and conditions listed above. I further agree that my failure to pay will obligate me to pay all court costs, attorney and collections fees incurred by McGarrett AC & Heating. The unpaid balance of accounts not paid in full 30 days after the date of the completed job will be subjected to 3% per month service charge for 3 months time from there if the payment still has not been received the unpaid balance due will be double the total of the original amount. McGarrett AC & Heating remains the owner of all material and equipment and reserves the right to repossess said material and equipment in the event of nonpayment.

Authorization for Repair: You hereby authorize to perform at the above address. It is understood that full payment is due upon completion of job unless previous arrangements have been made.

Signature \_\_\_\_\_ Date \_\_\_\_\_

TOTAL SUMMARY	
TOTAL MATERIALS	\$
LABOR	\$ 90.00
SUBTOTAL	\$
TAX <input type="checkbox"/> 8.25 <input type="checkbox"/> 7.25	\$
<b>GRAND TOTAL</b>	<b>\$ 90.00</b>