



Follow Up Inspection Report

Client Natasha Maryam Latifi

Address 6611 Etchstone Dr Spring, TX 77389

Date 10 / 02 / 2024 Time 11:30

Inspector Kelly Oldenkamp TREC# 21667

Reported Deficiency _____ Deficiency Fixed _____

- Inspector was given several items to check to make sure they were completed. That list was the following, but not limited too the items on the list.
- GFCI in attic, cover plates installed, wire spliced installed in junction boxes, bushings installed in service panel, sealant around light fixtures, smoke detectors installed, hydro massage tub, opener light, toilet valve handle, sealant strip attic ladder, self closing apparatus to garage door, secure soffit vents, collar tie repaired, seal all exterior windows and doors. YES / NO

By: Credit Card / Check # _____ / Cash TOTAL\$ 200



TexasPremiumInspections.com
Texas Premium Inspections

972-251-3014