

Replacement list for 6519 Bluestone.

Exterior:

Replaced damaged siding and trimming throughout.

Replaced Exterior Front/Back door.

Full Paint.

New concrete patio deck in backyard.

New fencing.

HVAC system serviced inside and outside unit.

New garage door opener.

Interior:

Full Paint.

New granite countertops.

New hardware.

New appliances.

New sink angle-stop valves/plumbing throughout.

New sinks and faucets.

New shower and tub trim.

New Flooring throughout.

New Carpet.

New Lighting and fan fixtures.

New air vents throughout.